

## Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		1		1		1			
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044		1		1		1			
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>0</b>	<b>3</b>	<b>0</b>	<b>3</b>	<b>0</b>	<b>3</b>	<b>0</b>	<b>0</b>	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	2		1		1				<b>1-Still</b>
2	NLG	144	988		7		7		7			
3	MDK	107	933	1	3	1	3	1	3			
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>3</b>	<b>10</b>	<b>2</b>	<b>10</b>	<b>2</b>	<b>10</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>3</b>	<b>13</b>	<b>2</b>	<b>13</b>	<b>2</b>	<b>13</b>	<b>0</b>	<b>0</b>	

TSSPDCL - LMRC / Corporate office

Date: 28.08.2018

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Shadnagar	Stem Core	33KV	Shadnagar	11.00	16.25	05.25	LV's PoI Out	Insulator Failed and Y Phase Pad Clamp Replaced Line Side	Stem Core	-
2		Kothur	Saint Gobain	33KV	Shadnagar	13.35	00.00	10.25	E/L	Break Down Not Rectified Due to 33KV Cable Kit Failure at Thimmapur Village	Kothur	-
1	MDK	Jogipet	Chitkul	33KV	Jogipet	09.10	14.25	05.15		BD Due to Pin Binding near by Annasagar Village	Chitkul	-

TSSPDCL - LMRC / Corporate office

Date: 28.08.2018

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Reddygudem	Reddygudem	11KV	Suryapeta	10.45	12.50	02.05	E/L	Insulator failure	-
2		B.Vellemla	Avuravani	11KV	Nalgonda	05.00	08.00	03.00	E/L	11KV Jumper cut	-
3		Mushampally	Mushampally	11KV	Nalgonda	06.30	10.00	03.30	E/L	11KV Jumper cut	-
4		Mushampally	Muthyalammagudem	11KV	Nalgonda	06.00	09.00	03.00	E/L	11KV Jumper cut	-
5		Paladugu	Dathappagudem	11KV	Bhongiri	04.00	08.30	03.30	E/L	11 KV Pin Insulator failure	-
6		Palakeedu	Palakeedu	11KV	Huzurnagar	10.15	12.00	01.45	E/L	11KV Jumper cut	-
7		Nandipahad	Nandipahad	11KV	Miryalaguda	04.15	06.20	02.05	E/L	Insulator failure	-
1	MDK	Sardhana	Jakkannapet	11KV	Medak	00.30	12.05	11.35		B/d due to insulater burst	-
2		Rangampet	Rangampet	11KV	Medak	10.35	13.35	03.00		B/d due to jumper cut.	-
3		Cheryal	Turbovent	11KV	Sangareddy	16.30	19.30	03.00		B/d due to Insulater Burst	-
1	RR N	Athiwelly	SPIC	11KV	Medchal	16.30	18.16	01.46	BD	CT Failed & Breaker problem(Back feeding arranged to 11KV Somaram Feeder )	-
1	RR E	Yadgarpally	Thimaipally	11KV	Keesara	09.20	09.50	00.30		Bird fallen on T/F at Thmaipaly village	-
1	HYD C	A.C.Guards	Shanthy Nagar	11KV	VII	18.32	19.47	01.15	All Indication	Jumper cut at Thaiva Hotel	-