

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	48	158									
2	NLG	18	406									
3	MDK	92	383									
4	RR(S)	40	201		1		1		1			
5	RR(N)	82	407		2		2		2			
6	RR(E)	38	360		2		2		2			
7	Hyd	186	1014		2		2		2			
	Total	504	2929	0	7	0	7	0	7	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	110	969	1		1		1				
2	NLG	150	948	1	2	1	2	1	2			
3	MDK	87	828		1		1		1			
4	RR(S)	31	338									
5	RR(N)	8	48									
6	RR(E)	18	89									
	Total	404	3220	2	3	2	3	2	3	0	0	
	Grand Total	908	6149	2	10	2	10	2	10	0	0	

TSSPDCL - LMRC / Corporate office

Date: 11.08.2017

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Kalwakurthy	Rachur	33KV	Jadcherla	08.35	10.25	01.50	E/L	Pin insulator failed and replaced near srisailam crass road	Rachur	-
1	NLG	Mattampally	DCL	33KV	Huzurnagar	07.40	10.50	03.10	EL/OL	33 KV Jumper cut at Mattampally (v)		-

TSSPDCL - LMRC / Corporate office

Date: 11.08.2017

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Pamanagundla	Pittampally	11KV	Suryapet	09.56	11.40	01.44	E/L	11Kv Jumper cut	-
2		Marriguda	Kondur	11KV	Devarakonda	09.00	11.00	02.00	E/L	11kv jumper cut	-
1	MDK	Burugupally	Burugupally	11KV	Medak	10.10	12.10	02.00		B/D Due to Jumper Cut	-
1	RR S	Manikonda	Hanuman Nagar	11KV	RJNR	16.33	17.32	00.59		11 KV Insulator fail at Hanuman Nagar	-
1	RR N	Gachibowli	Sudharshan nagar	11KV	Gachibowli	14.30	16.25	01.55		Pole damage at Gachibowli SS opposite	-
2		Ayyappa Society	Parwath nagar	11KV	Gachibowli	07.55	09.40	01.45		11kv End kit failed and Lines twisted at Govt School	-
1	RR E	AUTO NAGAR	HUDASAI NAGAR	11KV	SAROOR NAGAR	17.40	20.25	02.45	EL	11KV HUDASAINAGAR LOAD BACK FEEDING SOUTHENDPARK	-
2		ANAJPER	SRNR	11KV	IBPM	17.40	20.10	02.40	EL	DTR AB SWITCH OPEN AT ANAJPER	-
1	HYD N	I.D.P.L	Shivalayam	11KV	VI	07.30	08.45	01.15	All Indication	Cable fault	Arranged B/F on 11KV Obulam fdr
2		Bowenpally	Kalinga Enclave	11KV	VI	17.15	18.30	01.15	EL	Disc Insulator flash over at Kalinga Enclave	-----