

**Status Report on Breakdowns (Urban / Rural)****Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	48	158									
2	NLG	18	406									
3	MDK	92	383									
4	RR(S)	40	201									
5	RR(N)	82	407									
6	RR(E)	38	360									
7	Hyd	186	1014		2		2		2			
	<b>Total</b>	<b>504</b>	<b>2929</b>	<b>0</b>	<b>2</b>	<b>0</b>	<b>2</b>	<b>0</b>	<b>2</b>	<b>0</b>	<b>0</b>	

**Rural**

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	110	969	2		2		2				
2	NLG	150	948	1	6	1	6	1	6			
3	MDK	87	828		2		2		2			
4	RR(S)	31	338									
5	RR(N)	8	48									
6	RR(E)	18	89									
	<b>Total</b>	<b>404</b>	<b>3220</b>	<b>3</b>	<b>8</b>	<b>3</b>	<b>8</b>	<b>3</b>	<b>8</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>908</b>	<b>6149</b>	<b>3</b>	<b>10</b>	<b>3</b>	<b>10</b>	<b>3</b>	<b>10</b>	<b>0</b>	<b>0</b>	

TSSPDCL - LMRC / Corporate office

Date: 23.08.2017

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Marikal	Gunmukla	33KV	Mahabubnagar	02.40	10.15	07.35	E/L&O/L	Pin Insulator Replaced at Pole No 81 Near to PSR Power Plant	Gunmukla	-
2		Thirmalaipally	Kothakota	33KV	Wanaparthi	02.10	06.40	04.30	E/L	Insulator Flash Over at Kothakota By Pass	Kothakota	Load Diverted to 33KV Veltor Feeder at 6:40Hrs
1	NLG	Ramannapet	Aroor	33KV	Nalgonda	14.00	15.30	01.30	E/L	Breaker mechanical problem	Aroor	-

TSSPDCL - LMRC / Corporate office

Date: 23.08.2017

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Aregudem	Pedda Kaparthy	11KV	Nalgonda	04.45	07.00	02.15	E/L	11 KV line disc failure	-
2		Thatipamula	Sriram thanda	11KV	Suryapet	08.00	10.30	02.30	E/L	Tree branch fallen	-
3		Addagudur	Addaguduru	11KV	Bhongir	05.00	09.30	04.30	EL	Tree Branches on Line at Gattusingaram	-
4		Marriguda	Kondur	11KV	Devarakonda	07.00	10.00	03.00	EL	11kv jumper cut	-
5		Dirsincherla	Somaram	11KV	Huzurnagar	06.00	09.45	03.45	EL	Due to 11Kv Jumper cutted near Somaram village	-
6		Keethavarigudem	Kothagudem	11KV	Huzurnagar	03.00	11.00	08.00	EL	Due to 11kv line cutted near Kothagudem village	-
1	MDK	Narsapur	Reddypally	11KV	Medak	06.00	08.45	02.45		B/D Due to tree Branches fallen on 11KV line near Reddy pally (V)	-
2		B.B.Pur	Burugupally	11KV	Medak	07.15	08.05	00.50		B/D Due to Insulator failure at Burgupally (V)	-
1	HYD S	Falaknuma	Farooq Nagar	11KV	III	18.35	19.35	01.00	OL-Rph	HT Jumper Cut at Irfan Hotel	-
1	HYD C	Golnaka	Moulana Azad Nagar	11KV	II	03.36	07.50	04.14	EL,OL-Bph	Cable fault	Arranged B/F on 11KV Prabhat & 11KV C.C.S.Hospital feeders