

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	48	158									
2	NLG	18	406									
3	MDK	92	383									
4	RR(S)	40	201									
5	RR(N)	82	407									
6	RR(E)	38	360									
7	Hyd	186	1014		3		3		3			
	Total	504	2929	0	3	0	3	0	3	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	110	969									
2	NLG	150	948		3		3		3			
3	MDK	87	828									
4	RR(S)	31	338									
5	RR(N)	8	48									
6	RR(E)	18	89									
	Total	404	3220	0	3	0	3	0	3	0	0	
	Grand Total	908	6149	0	6	0	6	0	6	0	0	

TSSPDCL - LMRC / Corporate office

Date: 11.12.2017

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Aipoor	Kotapahad	11KV	Suryapet	07.30	10.00	02.30	E/L	11Kv Line cut	-
2		Addaguduru	Addaguduru	11KV	Bhongir	02.00	05.00	03.00	E/L	11KV Jumper snapped at Gattusingaram SS-2	-
3		Alair	Ch.Kandukur	11KV	Bhongir	02.00	05.00	03.00	E/L	11KV Line snapped at Basannagudem	-
1	HYD S	Kandikal Gate	G.M.Chowni	11KV	Charminar	01.55	03.20	01.25	EL	I/C Cable fault	Arranged B/F on 11KV Ravindra Naik Nagar fdr
2	HYD C	A.S.R.Raju Nagar	L.I.C Office	11KV	Mehdipatnam	05.50	07.30	01.40	OL	UG Cable fault at Habeeb Arcade	-----
3		Gudi Malkapur	Murad Nagar	11KV	Mehdipatnam	11.58	13.36	01.38	EL	Cable fault	Arranged B/F on 11KV LIC Office feeder

TSSPDCL - LMRC / Corporate office

Date: 11.12.2017

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	mbnr						NIL					-
2	nlg						NIL					-
3	mdk						NIL					-
4	RR S						NIL					-
5	RR N						NIL					-
6	RR E						NIL					-
7	HYD						NIL					-