

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	48	158									
2	NLG	18	406									
3	MDK	92	383									
4	RR(S)	40	201									
5	RR(N)	82	407									
6	RR(E)	38	360									
7	Hyd	186	1014		1		1		1			
	Total	504	2929	0	1	0	1	0	1	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	110	969		1		1		1			
2	NLG	150	948		4		4		4			
3	MDK	87	828									
4	RR(S)	31	338									
5	RR(N)	8	48									
6	RR(E)	18	89									
	Total	404	3220	0	5	0	5	0	5	0	0	
	Grand Total	908	6149	0	6	0	6	0	6	0	0	

TSSPDCL - LMRC / Corporate office

Date: 26.12.2017

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Janampet	Moosapet	11KV	Jadcherla	11.40	12.35	00.55		11 KV Wire Cut Near Moosapet(V)	-
1	NLG	Palakaveedu	Nagireddigudam	11KV	Huzurnagar	10.00	11.00	01.00	EL/OL	Due to 11kv line cutted near Nagireddigudam village	-
2		Huurnagar-2	Lingagiri	11KV	Huzurnagar	08.00	09.00	01.00	EL	Due to 11kv line cutted near Lingagiri village	-
3		Karivirala	Keshavapuram	11KV	Huzurnagar	11.50	14.10	02.20	EL	Due to 11kv Disk failure near Keshavapuram village	-
4		Annaram	Annaram	11KV	Suryapet	13.00	14.30	01.30	E/L	Jumper cut	-
1	HYD N	Bowenpally	B.B.R Hospital	11KV	Bowenpally	05.50	08.05	02.15	EL,OL-Rph	Cable fault	Arranged B/F on 11KV Ferozguda fdr

TSSPDCL - LMRC / Corporate office

Date: 26.12.2017

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBN				NIL							-
2	NLG				NIL							-
3	MDK				NIL							-
4	RRS				NIL							-
5	RR E				NIL							-
6	RR N				NIL							-
7	HYD N				NIL							-
8	HYD S				NIL							-
9	HYD C				NIL							-