

**Status Report on Breakdowns (Urban / Rural)****Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	48	158									
2	NLG	18	406									
3	MDK	92	383									
4	RR(S)	40	201									
5	RR(N)	82	407		1		1		1			
6	RR(E)	38	360	1	2	1	2	1	2			
7	Hyd	186	1014		2		2		2			
	<b>Total</b>	<b>504</b>	<b>2929</b>	<b>1</b>	<b>5</b>	<b>1</b>	<b>5</b>	<b>1</b>	<b>5</b>	<b>0</b>	<b>0</b>	

**Rural**

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	110	969	1	1	1	1	1	1			
2	NLG	150	948		6		6		6			
3	MDK	87	828	2	5	2	5	2	5			
4	RR(S)	31	338									
5	RR(N)	8	48									
6	RR(E)	18	89									
	<b>Total</b>	<b>404</b>	<b>3220</b>	<b>3</b>	<b>12</b>	<b>3</b>	<b>12</b>	<b>3</b>	<b>12</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>908</b>	<b>6149</b>	<b>4</b>	<b>17</b>	<b>4</b>	<b>17</b>	<b>4</b>	<b>17</b>	<b>0</b>	<b>0</b>	

TSSPDCL - LMRC / Corporate office

Date: 20.06.2017

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Kodangal	Kothur	33KV	Mahabubnagar	16.15	17.00	00.45	E/L	Break down Alternate Supply Arranged at 220KV Tador SS at 17:00Hrs No Visible fault	Kothur	Break down Alternate Supply Arranged at 220KV Tador SS at 17:00Hrs
1	MDK	Narayankhed	Poosalpad	33KV	Jogipet	15.10	22.00	06.50		B/D Due to Jumper Cut and Conductor snapped	Poosalpad	-
2		Pedda Shankarampet	Regode	33KV	Jogipet	15.30	21.05	05.35		B/D Due to 2Nos Insulator failure	Regode	-
1	RR E	Ibrahimpattanam	Mall	33KV	Saroomnagar	11.26	14.55	03.29		33KV Iron Pole Bended at Gurunanak College	Mall	-

TSSPDCL - LMRC / Corporate office

Date: 20.06.2017

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Kotakonda	Bandagonda	11KV	Mahabubnagar	00.00	11.30	11.30		11KV pole damage at Namallapally (Vi)	-
1	NLG	Gaddipally	Gaddipally	11KV	Huzurnagar	11.30	13.30	02.00	EL	11 KV Line snapped at Gaddipally village	-
2		Anneparthy	Cherlapally	11KV	Nalgonda	05.00	07.30	02.30	E/L	11 KV line cut	-
3		Anneparthy	Cherlapally	11KV	Nalgonda	04.00	06.00	02.00	E/L	11 KV line cut	-
4		Kopple	A.B.Colony	11KV	Devarakonda	12.30	15.30	03.00	OL	11kv jumper cutting	-
5		Anathram	Hanumapur	11KV	Bhongir	09.00	12.15	03.15	EL	11KV Line snapped Usnavada	-
6		Chedella	Chedella	11KV	Suryapet	08.00	10.40	02.40	E/L	11KV Insulator failed	-
1	MDK	Medak	Komtoor	11KV	Medak	11.00	12.15	01.15		B/D Due to tree branches fallen on the line	-
2		Rajpally	Balanagar	11KV	Medak	11.00	13.00	02.00		B/D Due to tree branches fallen on the line	-
3		Chippalthurthy	Jakkapally	11KV	Medak	02.00	07.00	05.00		B/D Due to 11KV Jumper cut and conductor snapped	-
4		Siripura	Govindrajpally	11KV	Medak	02.00	06.00	04.00		B/D Due to 11KV Conductor snapped	-
5		Dundigal	DRF	11KV	Medak	05.00	08.00	03.00		B/D Due to Jumper cut at Annaram village	-
1	RR N	Kistapur	Welset	11KV	Medchal	17.55	19.30	01.35	BD	11KV Pin Insulator failed at Satyasai Company Ravalkole	-
1	RR E	Cherlapally-I	Phase-I	11KV	Sainikpuri	11.15	12.30	01.15		11Kv Pin Insulator & Disk failed at Phase-II (L.Insp Kishan)	-
2		Mohan Nagar	Vidyuth Nagar	11KV	Sarooranagar	05.47	07.08	01.21		11KV Insulator fail at Kothapet	-
1	HYD S	Kandikal Gate	Gazimillath Colony	11KV	III	12.20	14.10	01.50	EL,OL	Big tree fallen on Lines at Dalchand Bazar & HT Line snapped at Flyover Bridge	-
1	HYD C	Zamisthanpur	L.N.Nagar	11KV	II	10.14	11.34	01.20	EL,OL-Bph	Cable End Kit failed at Ashok Nagar	-