

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	48	158									
2	NLG	18	406									
3	MDK	92	383									
4	RR(S)	40	201		3		3		3			
5	RR(N)	82	407		9		9		9			
6	RR(E)	38	360		3		3		3			
7	Hyd	186	1014		1		1		1			
	Total	504	2929	0	16	0	16	0	16	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	110	969	7	2	7	2	7	2			
2	NLG	150	948	1	15	1	15	1	15			
3	MDK	87	828	5		5		5				
4	RR(S)	31	338		1		1		1			
5	RR(N)	8	48									
6	RR(E)	18	89									
	Total	404	3220	13	18	13	18	13	18	0	0	
	Grand Total	908	6149	13	34	13	34	13	34	0	0	

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Gadwal	Oil Seed	33KV	Gadwal	23.35	02.35	03.00	E/L	AB switch failed	Oil Seed	-
2		Alampur	Alampur	33KV	Gadwal	20.25	23.04	02.39	E/L	Insulator Flash Over Near Alampur Road	Alampur	-
3		Alampur	Shanthinagar	33KV	Gadwal	20.30	22.45	02.15	E/L	Tree Fallen on the 33Kv Line Near Chulkala Vagu	Shanthinagar	-
4		leeza	Mitta Doddy	33KV	Gadwal	19.20	20.05	00.45	E/L	Back Feeding supply Taken to 33KV Gattu Feeder at 20:05Hrs and Supply Stud OK Mitta Doddy Feeder Supply Dark	Mitta Doddy	Back Feeding supply Taken to 33KV Gattu Feeder at 20:05Hrs and Supply Stud OK Mitta Doddy Feeder Supply Dark
5		Polepally	Gangapur	33KV	Jadcherla	18.30	19.00	00.30	E/L	Back Feeding supply Taken to 33KV Midjil Feeder at 19:00Hrs and Supply Stud OK	Gangapur	Back Feeding supply Taken to 33KV Midjil Feeder at 19:00Hrs and Supply Stud OK
6		Achampet	Veltoor	33KV	Nagarkurnool	18.45	20.25	01.40	E/L	Tree Fallen on the Line near Vetoor Village	Veltoor	-
7		Nagarkurnool	Manthathi	33KV	Nagarkurnool	23.15	07.47	08.32	E/L	B Phase Jumper Reconnection Line Isolator to Line Jumper at 132KV SS Nagarkurnool	Manthathi	-
1	NLG	Shouligouram	Addaguduru	33KV	Bhongir	03.00	06.00	03.00	EL	Tree Branches Fallen On Line		-
1	MDK	Jogipet	Citkul	33KV	Jogipet	06.25	11.25	05.00		B/D due to Conductor sanped near Chamudeshwari Temple.	Citkul	-
2		Zaheerabad	Hadnoor	33KV	Zaheerabad	07.00	15.30	08.30		B/D due to Insulator failed.	Hadnoor	-
3		Zaheerabad	Jharasangam	33KV	Zaheerabad	16.00	18.45	02.45		B/D duet to Jumper cut	Jharasangam	-
4		Medak	Shankarampet	33KV	Medak	14.12	15.10	00.58		B/D duet to Jumper cut at Govvalapally SS.	Shankarampet	-
5		Chegunta	Narsingi	33KV	Toopran	13.50	15.40	01.50		B/D duet to Jumper cut near Narsingi Village.	Narsingi	-

TSSPDCL - LMRC / Corporate office

Date: 23.06.2017

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Kalwakurthy	Kotra	11KV	Jadcherla	11.35	14.15	02.40		11KV Insulator Failure Near Ramnagar Thanda	-
2		Bhoothpur	Amistapur	11KV	Jadcherla	07.00	11.30	04.30		11KV Line Phase to Phase Near Hassnapur village	-
1	NLG	SV College	Loyala Xpress	11KV	Suryapet	04.00	06.45	02.45	E/L	Disk faild	-
2		Penpahad	SR Palem	11KV	Suryapet	07.00	10.00	03.00	E/L	11KV Jumper cut	-
3		Kethapally	Inupamala	11KV	Suryapet	08.20	11.30	03.10	E/L	11KV Jumper cut	-
4		B.p.pally	Muktapur	11KV	Bhongir	02.00	05.00	03.00	EL	11KV Line snapped at Mukthapur	-
5		B.p.pally	Revanpally	11KV	Bhongir	02.00	05.00	03.00	EL	Tree Branches On Line	-
6		Paladugu	Duppelly	11KV	Bhongir	02.00	06.00	04.00	EL	11KV Insulator failed	-
7		Chityala	Yelikatte	11KV	Nalgonda	03.00	07.00	04.00	EL	11 KV Line Jumper Cut	-
8		Mamidala	Godavarigudem	11KV	Nalgonda	09.00	11.00	02.00	EL	11 KV Line Jumper Cut	-
9		Mamidala	Mamidala	11KV	Nalgonda	11.20	14.00	02.40	EL	11 KV Line Jumper Cut at SS-6	-
10		Yennaram	Suraram	11KV	Nalgonda	04.00	08.30	04.30	EL	11 KV Insulator Failure	-
11		Urumadla	Yelikatte	11KV	Nalgonda	03.00	07.30	04.30	EL	11 KV Ilne Melting at SS-4	-
12		Disincherla	Yellapuram	11KV	Huzurnagar	03.00	07.10	04.10	EL	11Kv Insulator failure near Yellapuram village	-
13		Nadigudem	Krishnanagar	11KV	Huzurnagar	03.00	06.50	03.50	EL	Due to Jumper cut near Krishnanagar village	-
14		Siripuram	Siripuram	11KV	Huzurnagar	03.00	06.00	03.00	EL	Tree branch fall on 11Kv line near Siripuram village	-
15		Mamillagudem	Thummalapally	11KV	Huzurnagar	07.00	11.00	04.00	EL	Jumper cut near Thummalapally village	-
1	RR S	CBIT	Mobitower	11KV	RJNR	16.38	18.50	02.12	EL/BD	Tree fallen on 11kv line at South Indian Bank Khanapur	-
2		Vanasthalipuram	B N Reddy	11KV	CPT	16.40	17.20	00.40	EL/BD	Flexi Fallen on 11kv line at SBI Bank, BN Reddy	-
3		Leninagar	Dhatu nagar	11KV	CPT	00.30	01.20	00.50	EL/BD	DTR Problem at BDL Colony	-
4		Yellakonda	Mubarakpur	11KV	VKB	17.30	19.10	01.40	EL	11KV line shaped at Mubarakpur village	-

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	RR N	JNTU	Gokul Plots	11KV	GCB	10.50	11.50	01.00	BD	11kv Line Pin-Insulator failed at Plot No.1000, Phase-II, B.S.Nagar	-
2		L&T Infosity	PJR Nagar	11KV	GCB	14.15	15.15	01.00	BD	11kv Line Pin-Insulator failed at Children Park, Telecom Nagar	-
3		Nanakramguda	Manjeera	11KV	GCB	13.58	17.32	03.34	BD	11kv Line Pin-insulator failed at Manjeera Main Gate, and 11 Line Jumper cut at Muppa Constructions	-
4		Bachupally	SMS	11KV	KKP	10.40	11.20	00.40	BD	Lezard Fallon the PinInsulater opp: HotSpotat Bollaram	-
5		Mayurinagar	Cable	11KV	KKP	10.40	12.00	01.20	BD	11kv line PinInsulater Failure near Srinivasa Apt at Mayurinagar	-
6		Aleap	Doctors Colony	11KV	KKP	13.40	15.30	01.50	BD	11kv line PinInsulater Failure near Kakathiya Hills at Pragathinagar	-
7		Aleap	Doctors Colony Cable	11KV	KKP	10.23	11.23	01.00	BD	Tree Branchesh Fallon 11kv line at plot: 1162 ,Pragathinagar	-
8		Bahadurpally	IDA-II	11KV	KKP	13.35	15.08	01.33	BD	11kv line PinInsulater Failure near SMS SteelCompany,Bahadurpally	-
9		Medchal	Navadurga	11KV	MDCL	13.30	15.00	01.30	BD	11KV Pin Insulator failed near Sleep Well Company	-
1	RR E	Uppal	Raghavendra nagar	11KV	Habsiguda	00.10	02.10	02.00		AB cable fail at Bank colony	-
2		Keesara	Ankireddypaily	11KV	Habsiguda	08.05	09.05	01.00		Pin Insulator failed at Ankireddypally village	-
3		RFC	ANAJ PER AGL	11KV	Saroor Nagar	13.20	15.10	01.50		TREE BRCHANS FOLLOW ON 11KV LINE AT ANAJ PER	-
1	HYD N	Mytrivanam	Mytrivanam	11KV	IV	10.43	12.20	01.37	OL-Rph	Banner fallen on lines at Manjeera Square Apts	-