

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	48	158									
2	NLG	18	406									
3	MDK	92	383									
4	RR(S)	40	201									
5	RR(N)	82	407									
6	RR(E)	38	360									
7	Hyd	186	1014									
	Total	504	2929	0	0	0	0	0	0	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	110	969	2		2		2				
2	NLG	150	948	1	5	1	5	1	5			
3	MDK	87	828	1	1	1	1	1	1			
4	RR(S)	31	338									
5	RR(N)	8	48									
6	RR(E)	18	89									
	Total	404	3220	4	6	4	6	4	6	0	0	
	Grand Total	908	6149	4	6	4	6	4	6	0	0	

TSSPDCL - LMRC / Corporate office

Date: 02.11.2017

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Shali Gowraram	Gurjala	11KV	Nalgonda	12.30	14.40	02.10	EL	11KV Line Jumper Cut	-
2		Pamukunta	Pamukunta	11KV	Bhongir	09.00	12.30	03.30	EL	11K V Line snapped at Pamukunta	-
3		Pamukunta	Jala	11KV	Bhongir	11.50	14.10	02.20	EL	3 PH DTR Failure Near Jala	-
4		IDA	IDA	11KV	Bhongir	06.15	07.15	01.00	EL	11KV Line Snapped at House board	-
5		Janpahad	Janpahad	11KV	Huzurnagar	06.00	09.00	03.00	EL	11KV Line Jumper Cut	-
1	MDK	Ankshapur	Ankshapur	11KV	Siddipet	06.40	09.50	03.10		B/D due to Insulator fail	-

TSSPDCL - LMRC / Corporate office

Date: 02.11.2017

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Ghanpur	Lattupally	33KV	Wanaparthi	08.04	09.25	01.21	O/L	Alternate Supply Arranged to 33KV Bijinapally SS Feeder Supply Stud Ok At 09:25Hrs, 33KV line conductor replacement near Manganoor village		-
2		Alampur	Shanthinagar-I	33KV	Gadwal	14.26	16.06	01.40	E/L	AB Switch open at Paipad Metal , Tree Branch follen on the lien and removed at Shanthinagar		-
1	NLG	132 KV Ramapuram	Thoggarai	33KV	Huzurnagar	10.30	13.20	02.50	O/L	JUMPER CUT		-
1	MDK	Narsapur	Reddypally	33KV	Medak	03.40	06.20	02.40		B/d due to Conductor snapped.		-