

**Status Report on Breakdowns (Urban / Rural)****Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	48	158									
2	NLG	18	406									
3	MDK	92	383									
4	RR(S)	40	201									
5	RR(N)	82	407		2		2		2			
6	RR(E)	38	360									
7	Hyd	186	1014	1		1		1				
	<b>Total</b>	<b>504</b>	<b>2929</b>	<b>1</b>	<b>2</b>	<b>1</b>	<b>2</b>	<b>1</b>	<b>2</b>	<b>0</b>	<b>0</b>	

**Rural**

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	110	969	1		1		1				
2	NLG	150	948	1	5	1	5	1	5			
3	MDK	87	828	1	3	1	3	1	3			
4	RR(S)	31	338									
5	RR(N)	8	48									
6	RR(E)	18	89									
	<b>Total</b>	<b>404</b>	<b>3220</b>	<b>3</b>	<b>8</b>	<b>3</b>	<b>8</b>	<b>3</b>	<b>8</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>908</b>	<b>6149</b>	<b>4</b>	<b>10</b>	<b>4</b>	<b>10</b>	<b>4</b>	<b>10</b>	<b>0</b>	<b>0</b>	

TSSPDCL - LMRC / Corporate office

Date: 06.11.2017

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Makthal	Krishna	33KV	Mahabubnagar	07.55	08.55	01.00	E/L	Bird Fallen on the Line	Krishna	Jumper open at Towards Krishna SS & Tangadi
1	NLG	Bibinagar	Bollepally	33KV	Bhongir	04.00	08.35	04.35	EL	33KV Line snapped in Touched the Y Phase	Bollepally	-
1	MDK	Thunkibollaram	Thunkibollaram	33KV	Siddipet	00.00	07.55	07.55		B/D due to Insulator failed	Thunkibollaram	-
1	HYD S	220KV Ch' Gutta	Kandikal Gate	33KV	Malakpet	14.20	14.45	00.25	EL,OL-Bph	Cable fault at Owasi Hospital	Kandikal Gate	Loads transferred onto 220KV Ch' Gutta SS via 33KV C.R.P.F. fdr

TSSPDCL - LMRC / Corporate office

Date: 06.11.2017

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Velugupally	Keshavarapuram	11KV	Suryapet	13.30	15.00	01.30	EL	Bird Fallen	-
2		Alingapuram	Gundlapahad	11KV	Huzurnagar	14.30	18.00	03.30	EL	11 KV LINE snapped at Gundlapahad village	-
3		Thogarrai	Kapugallu	11KV	Huzurnagar	03.00	06.00	03.00	EL	11 KV Jumper cut at Kapugallu village	-
4		N B Gudem	Redlakunta	11KV	Huzurnagar	10.10	11.30	01.20	EL	AB Switch Problem at Redlakunta viallge	-
5		Urumadlla	Elekate	11KV	Nalgonda	11.35	14.35	03.00	EL	11 KV Jumper Cut	-
1	MDK	B.B.Pur	Burugupally	11KV	Medak	03.50	17.56	14.06		B/D due to Insulator failed	-
2		Yenigandla	Yenigandla	11KV	Medak	06.20	12.20	06.00		B/D due to Jumper cut near Yengandla (V)	-
3		Palvancha	Palvancha	11KV	Medak	16.40	19.00	02.20		B/D due to Insulator failed	-
1	RR N	Medchal	Navadurga	11KV	Medchal	19.30	20.25	00.55	BD	11KV Conductor snapped at Ida Medchal	-
2		Aliabad	Majeedpur	11KV	Medchal	19.15	20.30	01.15	BD	Breaker problem in SS ( Backfeeding arranged from 11KV Bommarajpet Feeder )	-