

**Status Report on Breakdowns (Urban / Rural)****Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	48	158									
2	NLG	18	406									
3	MDK	92	383									
4	RR(S)	40	201									
5	RR(N)	82	407	1	1	1	1	1	1			
6	RR(E)	38	360									
7	Hyd	186	1014									
	<b>Total</b>	<b>504</b>	<b>2929</b>	<b>1</b>	<b>1</b>	<b>1</b>	<b>1</b>	<b>1</b>	<b>1</b>	<b>0</b>	<b>0</b>	

**Rural**

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	110	969									
2	NLG	150	948		6		6		6			
3	MDK	87	828	2	2	2	2	2	2			
4	RR(S)	31	338									
5	RR(N)	8	48									
6	RR(E)	18	89									
	<b>Total</b>	<b>404</b>	<b>3220</b>	<b>2</b>	<b>8</b>	<b>2</b>	<b>8</b>	<b>2</b>	<b>8</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>908</b>	<b>6149</b>	<b>3</b>	<b>9</b>	<b>3</b>	<b>9</b>	<b>3</b>	<b>9</b>	<b>0</b>	<b>0</b>	

TSSPDCL - LMRC / Corporate office

Date: 19.11.17

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MDK	Habsipur	Dubbak	33KV	Siddipet	9:25	14:00	4:35		Insulator failed	Dubbak	No
2		Kowdipally	venkatraopet	33KV	Medak	08.15	09.20	01.05		Tree branches fallen on the line	venkatraopet	No
1	RR N	132KV Medchal	33KV Devarayamjal	33KV	MDCL	12:41	14:30	1:49		33KV Pin Insulator failed at Radhika Garden	Devarayamjal	No

TSSPDCL - LMRC / Corporate office

Date: 19.11.17

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Cheedella	Mukundapuram	11KV	Suryapet	9:40	10:50	1:10	EL	Insulator failed	No
2		Mukundapuram	Mukundapuram	11KV	Huzurnagar	10.30	14.40	04.10	EL	Tree fallen on the line	No
3		Siripuram	Sripuram	11KV	Huzurnagar	02.40	08.25	05.45	EL	11KV Jumper cut at Siripuram Village	No
4		Nandaanam SS	Tukkapuram	11KV	Bhongir	05.00	07.30	02.30	EL	11KV Line snapped at Divvaya bala School	No
5		Bondugula ss	Godumakunta	11KV	Bhongir	08.00	10.05	02.05	EL	Pin binding failed	No
6		Alair	Alair Town	11KV	Bhongir	9:50	11:15	1:25	EL	Tree branches fallen on the line at Alair	No
1	MDK	Thornal	Appanapally	11KV	Siddipet	0:00	6:30	6:30		Insulator failed	No
2		Ragothampally	Ramakkapet	11KV	Siddipet	00.00	03.10	03.10		Jumper cut	No
1	RR N	Gowdavelly	IDA	11KV	Medchal	5:35	7:35	2:00		11KV Pin Insulator failed at Swastik engineering	No