

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	48	158									
2	NLG	18	406									
3	MDK	92	383									
4	RR(S)	40	201									
5	RR(N)	82	407	1	2	1	2	1	2			
6	RR(E)	38	360									
7	Hyd	186	1014		2		2		2			
	Total	504	2929	1	4	1	4	1	4	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	110	969	1	1	1	1	1	1			
2	NLG	150	948		2		2		2			
3	MDK	87	828									
4	RR(S)	31	338									
5	RR(N)	8	48									
6	RR(E)	18	89									
	Total	404	3220	1	3	1	3	1	3	0	0	
	Grand Total	908	6149	2	7	2	7	2	7	0	0	

TSSPDCL - LMRC / Corporate office

Date: 27.11.2017

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Marikal	Koukuntla	33KV	Mahabubnagar	11.50	15.45	03.55	E/L	Bard Fallen on the line near gotanpally Village	Koukuntla	Alternate Supply Arranged to 33KV Devarkadra Feeder at 13:30Hrs
1	RR N	132KV Medchal	33KV Steel mill	33KV	Medchal	00.10	02.57	02.47		33KV Steelmill Feeder Staywire Fallen on 33KV Medchal-II Line	33KV Steel mill	-

TSSPDCL - LMRC / Corporate office

Date: 27.11.2017

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Udithyal	Udithyal	11KV	Jadcherla	10.00	11.30	01.30		11 kv jumper cut near Udithyal	-
1	NLG	Penpahad	Penpahad Town	11KV	Suryapet	15.00	17.00	02.00	EL	Jumper cut	-
2		Mukundapuram	Dacharam	11KV	Huzurnagar	06.30	10.23	03.53	EL	Due to tree branch fall on 11Kv line near Dacharam village	-
1	RR N	Shameerpet	Shameerpet	11KV	Medchal	07.30	09.45	02.15		11KV Jumper cut & replacement near Shameerpet Lake	-
2		Subash Nagar	Pragatools	11KV	Medchal	19.48	20.50	01.02		11KV Cable failed at Hanuman Temple, Jeedimetla	-
1	HYD N	Patigadda	Rasoolpura	11KV	V	16.25	18.25	02.00	EL,OL	RMU to RMU Cable fault at Rasoolpura	-----
1	HYD C	Industrial Area	RTC X-Roads	11KV	II	20.00	22.35	02.35	EL	Cable fault	Arranged B/F on 11KV Dayara Market feeder