

TSSPDCL - LMRC / Corporate office

Date: 01.10.2017

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Wanaparthi	Kodair	33kv	Wanaparthi	16.55	00.00	07.05	E/L	Not Rectified	Kodair	-
2		Nagarkurnool	Manthathi	33kv	Nagarkurnool	15.30	17.30	02.00	E/L	2Nos Insulator Replacement near Chandu batla Gate Gate	Manthathi	-
3		Nagarkurnool	lthole	33kv	Nagarkurnool	15.20	18.20	03.00	E/L	Loads Diverting Nagarkurnool Feeders at 18:20Hrs Supply Stud Ok	lthole	-
1	HYD C	132KV Imlibun	Gosha Mahal	33kv	Mehdipatnam	12.15	12.25	00.10	OL	Cable End Kit failed at 132KV Imlibun SS of 33KV Imlibun - Gosha Mahal fdr	Gosha Mahal	Loads transferred onto 132KV Imlibun SS via 33KV Seetharam Bagh fdr

TSSPDCL - LMRC / Corporate office

Date: 01.10.2017

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Rajapur	Mallepally	11kv	Jadcherla	13.00	15.00	02.00		11KV wire cut near Ediganipally	-
1	NLG	Athmakur(S)	Gottimukkula gudem	11kv	Suryapet	10.00	13.00	03.00	EL	LINE CUT	-
2		Repala	N S gudem	11kv	Huzurnagar	02.00	09.00	07.00	EL	LINE SNAPPED	-
1	MDK	Nangnoor	Nagarajupally	11kv	Siddipet	08.20	14.50	06.30		B/d due to Insulater fail	-
2		Ponnala	Rangadampally	11kv	Siddipet	08.00	14.00	06.00		B/d due to Disk fail	-
3		Ramancha	Ramancha	11kv	Siddipet	05.00	10.00	05.00		B/d due to Disk fail	-
1	RR N	Nizampet	Bhavyas	11kv	Kukatpally	05.35	06.35	01.00	EI	11kv line Pin Insulater failure at BerliyFome bhavyas	-
2		DPPally-II	Indo Fab	11kv	Jeedimetla	03.35	06.30	02.55	EL	Sujatha Steel Company AB Switch Spark & Repaire { Due to Havy Rain }	-
1	RR E	Cherlapally-III	Gail	11kv	Sainikpuri	18.40	19.40	01.00		11KV Jumper cut at Gandhi Nagar Colony	-
2		Pocharam	Pocharam(V)	11kv	Keesara	19.05	20.45	01.40		11KV Pin Insulator failed at pocharam grama Panchayathi	-
3		Singapur	Annojiguda	11kv	Keesara	19.20	20.15	00.55		11KV Pin Insulator failed at Outer Ring Road	-
4		Rampally Dayara	Vanneguda	11kv	Keesara	20.15	21.10	00.55		11KV HG fuse insulator failed near Annapurna Function Hall	-
1	HYD N	Bhudevi Nagar	Gollaguda	11kv	Erragadda	21.10	22.40	01.30	EL	Disc Insulator flash over at 7 Temple	-

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	48	158									
2	NLG	18	406									
3	MDK	92	383									
4	RR(S)	40	201									
5	RR(N)	82	407		2		2		2			
6	RR(E)	38	360		4		4		4			
7	Hyd	186	1014	1	1	1	1	1	1			
	Total	504	2929	1	7	1	7	1	7	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	110	969	3	1	3	1	2	1	1		1 no.33kv still
2	NLG	150	948		2		2		2			
3	MDK	87	828		3		3		3			
4	RR(S)	31	338									
5	RR(N)	8	48									
6	RR(E)	18	89									
	Total	404	3220	3	6	3	6	2	6	1	0	
	Grand Total	908	6149	4	13	4	13	3	13	1	0	