

**Status Report on Breakdowns (Urban / Rural)****Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	48	158									
2	NLG	18	406									
3	MDK	92	383									
4	RR(S)	40	201		3		3		3			
5	RR(N)	82	407		1		1		1			
6	RR(E)	38	360		3		3		3			
7	Hyd	186	1014		2		2		2			
	<b>Total</b>	<b>504</b>	<b>2929</b>	<b>0</b>	<b>9</b>	<b>0</b>	<b>9</b>	<b>0</b>	<b>9</b>	<b>0</b>	<b>0</b>	

**Rural**

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	110	969	3	1	3	1	3	1			
2	NLG	150	948	1	6	1	6	1	6			
3	MDK	87	828	2	15	2	15	2	15			
4	RR(S)	31	338									
5	RR(N)	8	48									
6	RR(E)	18	89									
	<b>Total</b>	<b>404</b>	<b>3220</b>	<b>6</b>	<b>22</b>	<b>6</b>	<b>22</b>	<b>6</b>	<b>22</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>908</b>	<b>6149</b>	<b>6</b>	<b>31</b>	<b>6</b>	<b>31</b>	<b>6</b>	<b>31</b>	<b>0</b>	<b>0</b>	

## TSSPDCL - LMRC / Corporate office

Date: 06.10.2017

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Ieeza	T T Doddi	33KV	Gadwal	15.05	16.30	01.25	E/L	Lighting arrester fault near Uthanoor SS	T T Doddi	-
2		Marikal	Devarkadadra	33KV	Mahabubnagar	23.05	00.50	01.45	E/L	No fault found due to Rain	Devarkadadra	Alternate Supply Arranged from 33KV Koukuntla feeder at 00:50Hrs.
3		Maddur	Damargidda	33KV	Mahabubnagar	18.12	20.55	02.43	E/L	Pin Insulators failed and replaced near Kyathan Pally	Damargidda	-
1	NLG	Ramannapet	Aroor	33KV	Choutuppal	03.10	06.30	03.20	EL/OL	33KV Insulator failed near Laxmapur	Aroor	-
1	MDK	Palamakula	Gonepally	33KV	Siddipet	07.46	10.29	02.43		B/D Due to Pin Insulator Failure	Gonepally	-
2		Pashamailaram	EPIP P. Mailaram	33KV	Sangareddy	12.20	14.15	01.55		B/D Due to alternate supply given to EPIP feeder Tag on BPL Fedder	EPIP P. Mailaram	-

TSSPDCL - LMRC / Corporate office

Date: 06.10.2017

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Ponnakal	Vemula	11KV	Jadcherla	10.00	10.50	00.50		11 Kv Insulator Failure Near Bhavanamatha DTR Side.	-
1	NLG	Penpahad	potlapahad	11KV	Suryapet	07.30	11.00	03.30	E/L	Jumper cut	-
2		Rajapet	Ranikunta	11KV	Bhongir	05.00	08.30	03.30	EL	11KV Disk failed at Raniukunta	-
3		Bhongir ss	Raigiri Indus	11KV	Bhongir	06.00	11.00	04.00	EL	11Kv Insulator failed	-
4		Thoragal	Madaram	11KV	Nalgonda	10.00	12.30	02.30	EL	Insulator failed	-
5		Kethapally	Inupamula	11KV	Nalgonda	03.00	05.00	02.00	EL	Insulator failed	-
6		Shaligouraram	Utkur	11KV	Nalgonda	10.00	12.30	02.30	EL	Jumper cut	-
1	MDK	Mittapally	Yellupally	11KV	Siddipet	09.00	17.10	08.10		B/D Due to Insulator Failure	-
2		Nangunoor	Nagarajupally	11KV	Siddipet	09.00	16.50	07.50		B/D Due to Insulator Failure	-
3		Chinthamadaka	Machapur	11KV	Siddipet	09.50	12.08	02.18		B/D Due to Conductor Snapped	-
4		Dubbak	Dubbak	11KV	Siddipet	08.00	09.17	01.17		B/D Due tree branch fallen on the line	-
5		Gurralagondi	Malyal	11KV	Siddipet	10.22	11.15	00.53		B/D Due tree branch fallen on the line	-
6		Peddachikode	Peddachikode	11KV	Siddipet	07.30	13.00	05.30		B/D Due to Jumper Cut	-
7		Peddachikode	Achamaipally	11KV	Siddipet	07.25	12.00	04.35		B/D Due to Jumper Cut	-
8		Avancha	Avancha	11KV	Medak	10.00	13.00	03.00		B/D Due to tree Branch fallen on the line	-
9		Chippalthurty	Jakkapally	11KV	Medak	08.40	09.40	01.00		B/D Due to Jumper Cut	-
10		Kowdipally	Mohd Nagar	11KV	Medak	14.40	15.50	01.10		B/D Due to Jumper Cut	-
11		Narsingi	Narsingi	11KV	Medak	05.50	08.00	02.10		B/D Due to Conductor Snapped	-
12		Venkatraopet	Reddypally	11KV	Medak	10.40	11.41	01.01		B/D Due to Insulator Failure	-
13		Gadipeddapur	Gadipeddapur	11KV	Medak	01.05	10.40	09.35		B/D Due to Conductor Snapped	-
14		Medak	Kuchanpally	11KV	Medak	13.25	15.16	01.51		B/D Due to Insulator Failure	-
15		B.Bpur	Burugupally	11KV	Medak	08.22	13.20	04.58		B/D Due to Jumper Cut	-
1	RR S	APPA	Himayathsagar	11KV	RJNR	05.40	07.40	02.00	B/D	11KV Insulator failed at ORR	-
2		Ibrahimbagh	Peddamangalaram(I BGH)	11KV	RJNR	00.46	02.50	02.04	B/D	Bat fallen on 11KV Line at Opp SS	-
3		Puppallaguda	Alkapuri	11KV	IBGH	01.00	02.00	01.00	B/D	11KV Disc failed at Tuljaram Temple	-
1	RR N	J D M ss-I	J E T E L	11KV	JDM	01.20	02.33	01.13	EL	11kv Jumper Cut touched channel In sub station	-
1	RR E	Moula-Ali	Jawhar nagar	11KV	Sainikpuri	15.30	16.00	00.30	EL	Tree fallen on 11Kv line at SP naagr (LM Venkatesh)	-
2		Moula-Ali	Mirjalguda	11KV	Sainikpuri	16.00	16.10	00.10	EL	11Kv line Snapped at ZTC near Devi bar (L.Insp Ravi)	-
3		Sai Nagar	RNS Colony	11KV	Habsiguda	16.20	18.20	02.00		11KV Pin Insulator failed at Sai Nagar Colony	-

1	HYD N	MLA Colony	Kalinga	11KV	X	00.50	02.30	01.40	All Indication	No Visible Fault	Arranged B/F on 11KV Chiran Palace fdr
1	HYD S	Malakpet	Dabeerpura	11KV	VIII	14.45	16.50	02.05	EL	Disc Insulator flash over at IAZAA School	-