

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	48	158									
2	NLG	18	406									
3	MDK	92	383									
4	RR(S)	40	201		4		4		4			
5	RR(N)	82	407	2	7	2	7	2	7			
6	RR(E)	38	360		8		8		8			
7	Hyd	186	1014		14		14		14			
	Total	504	2929	2	33	2	33	2	33	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	110	969	1	2	1	2	1	2			
2	NLG	150	948		17		17		17			
3	MDK	87	828	2		2		2				
4	RR(S)	31	338	1		1		1				
5	RR(N)	8	48									
6	RR(E)	18	89									
	Total	404	3220	4	19	4	19	4	19	0	0	
	Grand Total	908	6149	6	52	6	52	6	52	0	0	

TSSPDCL - LMRC / Corporate office

Date: 08.10.2017

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Gadwal	Maldakal	33KV	Gadwal	03.51	09.05	05.14	E/L & O/L	Jumper Opened at Kakularam SS Supply Stud Ok	Maldakal	-
1	MDK	Narayankhed	Wasar	33KV	Jogipet	14.30	18.10	03.40		B/D due to Insulator fail near Ramthirtham Village.	Wasar	-
2		Narayankhed	Sirgapur	33KV	Jogipet	15.10	19.25	04.15		B/D due to Insulator fail near Venkatraopet Village.	Sirgapur	-
1	RR S	Puttapahd	Doma	33KV	Vikarabad	08.05	09.15	01.10	E/L	2 Nos 33 kv line Disc Insolaters failed near Bandenkacharla vg & Peerampally vg		Doma
1	RR N	132KV Medchal	33KV Kompally	33KV	Medchal	09.50	16.40	06.50	BD	BD declared and 33KV Cable end Kit Jumper Failed and replaced at Mypi Villa	33KV Kompally	-
2		132KV Medchal	33KV Bandamadaram	33KV	Medchal	14.01	15.56	01.55	BD	33KV Pin Insulator Failed at near by Gowdavelly SS	33KV Bandamadaram	-

TSSPDCL - LMRC / Corporate office

Date: 08.10.2017

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Christainpally	Palkonda	11KV	Mahabubnagar	08.40	09.40	01.00		11KV Disk failure at Eenadu Office (V)	-
2		Kothapally (C.C.K)	Gopanpet	11KV	Mahabubnagar	06.15	09.30	03.15		11KV Insulator Damage Near Karne (V)	-
1	NLG	Repala	Narsimhalagudem	11KV	Huzurnagar	03.00	06.00	03.00	E/L	11kv Disk failed at Narsimhalagudem (v)	-
2		Thogarrai	Ganapavarm	11KV	Huzurnagar	08.00	09.35	01.35	E/L	Transformer failed at Ganapavaram (v)	-
3		Gondiryala	Chimiryala	11KV	Huzurnagar	02.00	06.00	04.00	E/L	11kv jumper cut at Chimiryala (v)	-
4		Chilukur	Janakinagar thanda	11KV	Huzurnagar	06.50	10.50	04.00	E/L	11kv line snapped at Janakinagar thanda (v)	-
5		Kethepally	Kasangodu	11KV	Nalgonda	12.20	08.50	03.30	E/L	11Kv Disk Fialure	-
6		Pamanagundla	Pittampally	11KV	Nalgonda	08.40	11.00	02.20	E/L	HT/LT Melting	-
7		Chandupatla	Chandupatla Indus	11KV	Bhongir	02.00	06.00	04.00	E/L	Leather Facotroy AB Switch Failed	-
8		Nandanam	Telephone Exchange	11KV	Bhongir	01.00	06.00	05.00	E/L	Tree Branches Fallen On Line & Heavy rain	-
9		M.T.Pally	M.T.Pally AGL	11KV	Bhongir	05.00	09.00	04.00	E/L	11KV DTR Failed	-
10		N.G Bandal	V.R Pally	11KV	Bhongir	02.00	06.00	04.00	E/L	11KV Insulator failed at V.r Pally	-
11		Rajapet	Ranikunta	11KV	Bhongir	02.00	06.00	04.00	E/L	11KV Line snapped at Rajapet	-
12		Raghunathpur	Raghunathpur AGL	11KV	Bhongir	05.30	07.00	01.30	E/L	11KV Line snapped at Raghunathpur Village	-
13		Motakondur	Motakondur Indus	11KV	Bhongir	04.00	09.10	05.10	E/L	11KV Insulator failed	-
14		Choutuppal	Chinnakondur	11KV	Choutuppal	02.00	07.00	05.00	E/L	Single Ph DTR Failure Near Kondur Village	-
15		D.Nagaram	D.Nagaram	11KV	Choutuppal	02.00	07.00	05.00	E/L	11KV Diskfailed & Jumper Snapped Nagaram	-
16		Athmakur(S)	T.Penpahad	11KV	Suryapet	04.30	08.00	03.30	E/L	11Kv Insulator failed	-
17		Ramachandra Puram	Ramachandra Puram	11KV	Suryapet	22.00	03.00	05.00	E/L	11Kv Disk failed	-

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	RR S	NPA	Raghavendra colony	11KV	RJNR	09.00	10.33	01.33	B/D	11kv Disc Failed at Darshan doddi	-
2		Upparpally	Parmareddy hills	11KV	RJNR	06.05	07.25	01.20	B/D	lizard Fallen on 11kv Line at Pillar No.192	-
3		Rajendranagar	University	11KV	RJNR	14.42	15.52	01.10	B/D	11kv Insulator Failed at four pole structure SS Back side	-
4		Ibrahimbagh	Military-I	11KV	IBGH	09.26	10.20	00.54	B/D	Bird Fallen on 11kv Line at One more Nagar	-
1	RR N	Kompally	Petbasheerbagh	11KV	Medchal	00.30	02.00	01.30	BD	No Fault(Due to Rain)	-
2		Bowrampet	Bowrampet	11KV	JDM	01.15	10.50	09.35	EL	11kv Pin Insulator Failure At bowrampet	-
3		D P Pally	Bowrampet	11KV	JDM	04.30	06.10	01.40	EL	11kv Pin Insulator Failure At bowrampet	-
4		Medchal	Rural Kandlakoya	11KV	Medchal	04.30	07.00	02.30	BD	Tree fallen on the 11KV Line at SS Back side	-
5		Medicity	IDA-I	11KV	Medchal	01.15	02.50	01.35	BD	Tree fallen on the 11KV Line at Ganpur Village	-
6		Athiwelly	SPIC	11KV	Medchal	10.25	12.50	02.25	BD	11KV Pin Insulator failed at rekulabavi	-
7		Medicity	IDA-I	11KV	Medchal	15.10	17.05	01.55	BD	11KV Pin Insulator and Disc Failed at Medicity Hospital	-
1	RR E	AUTO NAGAR	AUTO NAGAR	11KV	Saroor Nagar	14.45	16.45	02.00		11KV DISK FAIL AT AUTONAGAR	-
2		BAGASINGNAGAR	POST OFFICE	11KV	Saroor Nagar	14.50	16.05	01.15		DTR INSULATOR FAIL AT BAPU NAGAR RD NO 6	-
3		Street No-8	Stadium	11KV	Habsiguda	08.48	09.49	01.01		CT/PT Problem & Cable disconnection at Stadium	-
4		Idauppal	Jersey	11KV	Habsiguda	14.27	16.00	01.33		Jumper replaced at Sravanthi electronics	-
5		Idauppal	Metro	11KV	Habsiguda	14.43	16.00	01.17		Due to rain, Polymer disc failed at PNR	-
6		Keesara	Kadevi	11KV	Keesara	16.10	08.30	16.20		11KV Pin Insulator failed near MRF Company showroom	-
7		P&T Colony	Budda Nagar	11KV	Keesara	11.20	11.50	00.30		11KV AB Switch sparked near Patel company at Budda Nagar	-
8		Cherlapally-I	Ramapally	11KV	Keesara	14.45	16.30	01.45		11KV Pin Insulator failed at Rampally to Cherlapally Road	-

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	HYD S	Malakpet	Komatiwadi	11KV	VIII	00.53	02.55	02.02	All Indication	HT Jumper cut at Darbar Maisamma Temple	-
2		Malakpet	Noorkhan Bazar	11KV	VIII	00.53	05.30	04.37	All Indication	Cable fault at Chaderghat & Loads normalised	-
3		Malakpet	Chaderghat	11KV	VIII	00.53	04.30	03.37	All Indication	HT Jumper cut at Balaji Sweet House	-
4		Salarjung	Darulshifa	11KV	III	01.45	03.00	01.15	EL,OL-Rph	DTR End Kit failed at Darulshifa Ground DTR (1No. DTR kept off)	-
5		Salarjung	Yakuthpura	11KV	VIII	02.25	04.20	01.55	All Indication	No Visible Fault	-
6		Miralam	Kala Pather	11KV	III	04.20	06.10	01.50	EL,OL-Rph	Cable fault at Shanthi Stall	-
7		Salarjung	Purani Haveli	11KV	III	04.40	06.55	02.15	All Indication	Cat fallen in RMU at Miralam Mandi	-
8		Salarjung	Yakuthpura	11KV	VIII	04.40	06.25	01.45	All Indication	Jumper cut at Darushifa Hospital	-
9		Falaknuma	Falaknuma OH	11KV	III	07.35	09.24	01.49	EL,OL-Rph	Cable fault at Falaknuma	-
10		Miralam	Jahanuma	11KV	III	12.45	13.50	01.05	EL,OL-R&Bph	No Visible Fault	-
11		Kandikalgate	Saibaba Nagar	11KV	III	17.15	18.50	01.35	EL	Pin Insulator flash over at Saibaba Nagar	-
1	HYD C	Golconda	O.U Colony	11KV	VII	14.15	16.20	02.05	EL	HT Service Pin Insulator flash over at O.U Colony	-
2		Bathkammakunta	Ahobilmutt	11KV	II	14.55	16.15	01.20	EL	Tree branches fallen on lines at Hotel Management	-
3		Lake View	APSEBEA	11KV	I	04.00	05.20	01.20	EL,OL-Rph	O/G AB Switch Jumper cut at SS	Arranged B/F on 11KV Satyam Computers fdr