

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	48	158									
2	NLG	18	406									
3	MDK	92	383									
4	RR(S)	40	201									
5	RR(N)	82	407	1	2	1	2	1	2			
6	RR(E)	38	360		2		2		2			
7	Hyd	186	1014		1		1		1			
	Total	504	2929	1	5	1	5	1	5	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	110	969	1		1		1				
2	NLG	150	948		9		9		9			
3	MDK	87	828		4		4		4			
4	RR(S)	31	338									
5	RR(N)	8	48									
6	RR(E)	18	89									
	Total	404	3220	1	13	1	13	1	13	0	0	
	Grand Total	908	6149	2	18	2	18	2	18	0	0	

TSSPDCL - LMRC / Corporate office

Date: 18.09.2017

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Repala	Repala	11kv	Huzurnagar	09.00	12.42	03.42	OL	Tree branch fall 11kv on Repala village	-
2		Thogarrai	GudiBanda	11kv	Huzurnagar	03.00	05.40	02.40	EL	11 kv line Snapped GudiBanda village	-
3		Durajpally	Durajpally Agl	11kv	Suryapet	04.50	06.25	01.35	EL	Jumper cut	-
4		Raghunathpur	Challuru	11kv	Bhongir	13.30	15.30	02.00	EL	Tree branches fallen On Line	
5		Paladugu	Dattappagudem	11kv	Bhongir	06.00	09.00	03.00	EL	Insulator failure	
6		Yennaram	Kakireni	11kv	Choutuppal	09.00	12.30	03.30	EL	11Kv Line snapped at Kakireni	
7		Eduloor	Chada	11kv	Nalgonda	06.00	08.30	02.30	EL	Insulator failure	-
8		Pamanagundla	Pittampally	11kv	Nalgonda	05.30	08.30	03.00	EL	11 KV Jumper cut	-
9		Madgulapally	Kukkadam	11kv	Nalgonda	07.00	09.45	02.45	EL	11Kv Line snapped	-
1	MDK	Jangapally	Jangapally	11kv	Siddipet	13.55	17.00	03.05		B/D due to Disk Failed	-
2		Kowdipally	Devulapally	11kv	Medak	02.15	07.00	04.45		B/D 11KV JUMPER CUT	-
3		Rangampet	Paithra	11kv	Medak	06.35	10.40	04.05		B/D DUE TO 33KV CLAMP CHANGED	-
4		EPIP-I	Chaitanya	11kv	Sangareddy	06.24	08.53	02.29		B/D due to conductor snaped at 2 places Near Sathyadeva chemical	-
1	RR N	JDM SS -I	JETL	11kv	Jeedimetla	06.40	07.40	01.00	BD	11kv line Jumper Cut At Sub-Station	
2		Kandlakoya	Goderj	11kv	Medchal	04.35	05.45	01.10	BD	Tree fallen on the 11KV Line at Kandlakoya	
1	RR E	BANDARAVIRALA	INDUSTRIAL	11kv	IBRAHIMPATNAM	09.10	11.15	02.05	EL	CT BT JUPER CUT AT UDAY COMPANY	-
2		KOTHAPET	NARSIMHAPURI COLONY	11kv	SAROORNAGAR	15.45	17.21	01.36	EL	11KV PIN INSULATER FAIL AT HUDACOLONY	-
1	HYD N	Gunrock	Subhash Nagar	11kv	Bowenpally	18.45	20.05	01.20	EL,OL-Bph	Tree branches fallen on lines at RTC Colony	

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Thirmalaipally	Veltoor	33kv	Wanaparthi	10.24	11.12	00.48	E/L	Breaker Problem	Veltoor	-
1	RR N	132KV Medchal	33KV Medchal-I	33kv	Medchal	06.03	08.33	02.30	BD	Tree Fallen on the 33KV Line at Forest Area,near Kistapur	33KV Medchal-I	-