

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		3		3		3			
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044		1		1		1			
	Total	606	3055	0	5	0	5	0	5	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	3		3		3				
2	NLG	144	988		5		5		5			
3	MDK	107	933	2		2		2				
4	SDPT			1	3	1	3	1	3			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	6	8	6	8	6	8	0	0	
	Grand Total	1082	6468	6	13	6	13	6	13	0	0	

TSSPDCL - LMRC / Corporate office

Date: 17.08.2018

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Midjil	Velgomula	33KV	Jadcherla	08.25	10.25	02.00	E/L	Pin Insulator Replaced near Wadala Village		-
2		Wanaparthi	Buddaram	33KV	Wanaparthi	12.20	16.20	04.00		33KV Breaker Problem		-
3		Alwal	Ippalapally	33KV	Shadnagar	18.30	21.50	03.20	EL	Pin insulator replaced near Vemul Narwa		-
1	MDK	Pashamailaram	Nandigama	33KV	Sangareddy	04.55	06.05	01.10		B/D Due to lightning arester failure.		-
2		Pashamailaram	EPIP -II	33KV	Sangareddy	14.48	15.40	00.52		B/D due to Jumper cut		-
3	SDPT	Mustyala	All feeders	33KV	Husnabad	10.15	10.45	00.30		LVS pull out		-

TSSPDCL - LMRC / Corporate office

Date: 17.08.2018

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Gundepuri	Gundepuri	11KV	Suryapeta	04.40	07.30	02.50	E/L	Disk failed	-
2		Narketpally	Mandra	11KV	Nalgonda	10.40	13.05	02.25	E/L	11KV Line Jumper cut	-
3		Thurkapally	Ajjalapuram	11KV	Nalgonda	12.40	15.50	03.10	E/L	11KV Insulator failure	-
4		Bethavolu	Chennaigudem	11KV	Huzurnagar	02.20	03.32	01.12	E/L	11KV Insulator failure	-
5		Karivirala	Keshavapuram	11KV	Huzurnagar	09.45	11.07	01.22	E/L	11KV Line Jumper cut	-
1	SDPT	33/11KV Mustyala	LV	11KV	Siddipet	11.25	14.30	03.05		Due to CT jumper burnt, same rectified	-
2		33/11KV Komuravelly	Kadavergu	11KV	Siddipet	19.20	23.50	04.30		3-ph supply OK, S-Ph supply breakdown	-
3		33/11KV Bejjanki	Regulapally	11KV	Siddipet	15.30	17.00	01.30		11KV insulator break same rectified	-
1	RR N	Dulapally	Karthikavanam	11KV	Medchal	14.32	16.03	01.31	BD	11KV Line Cut & Replaced at SS Opposite	-
2		Medchal	Medchal	11KV	Medchal	07.20	09.20	02.00	BD	HT/LT Line Cut & Replaced at Main Campus Backside	-
3		Jeedimetla-I	Thirumala	11KV	Jeedimetla	03.30	07.00	03.30	EL/OL	11kv Ab cable Failure Near beer company Phase-I	-
1	RR E	Yapral	Tulasi Garden	11KV	Sainikpuri	22.00	22.50	00.50		11Kv Disk failed at Auto Nagar X Road (AE/OP)	-
1	HYD N	Jana priya	Bharath nagar	11KV	Erragadda	05.07	06.20	01.13	All indications	Jumper cut at Bharath nagar fly over	-