

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	48	158									
2	NLG	18	406									
3	MDK	92	383									
4	RR(S)	40	201									
5	RR(N)	82	407		1		1		1			
6	RR(E)	38	360		3		3		3			
7	Hyd	186	1014									
	Total	504	2929	0	4	0	4	0	4	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	110	969									
2	NLG	150	948		5		5		5			
3	MDK	87	828	2		2		2				
4	RR(S)	31	338									
5	RR(N)	8	48									
6	RR(E)	18	89									
	Total	404	3220	2	5	2	5	2	5	0	0	
	Grand Total	908	6149	2	9	2	9	2	9	0	0	

TSSPDCL - LMRC / Corporate office

Date: 07.01.2018

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Cheedella	Gajulamalka Puram	11KV	Suryapet	11.20	13.20	02.00	E/L	Line cut	-
2		Alingapuram	Chennaipalem	11KV	Huzurnagar	20.00	00.00	04.00	E/L	11 kv line snapped at Chennaipalem village	-
3		Raghunadapalem	Raghunadapalem	11KV	Huzurnagar	04.10	05.10	01.00	E/L	11kv line snapped at Raghunadapalem village	-
4		Urumadla	Urumadla	11KV	Nalgonda	09.00	10.35	01.35	E/L	11KV jumper cut at SS-2	-
5		Ch.laxmapur	Madhapur	11KV	Bhongir	08.30	12.40	04.10	E/L	11KV Insulator failed at Madhapur Village	-
1	RR N	Bandamadaram	Srirangavaram	11KV	Medchal	15.10	20.05	04.55	BD	HT/LT Line melted at Bandamaram Village	-
1	RR E	Moula-Ali	Kailasagiri	11KV	Sainikpuri	17.49	18.40	00.51		11Kv UG Cable failure at Kailasagiri (AE/OP)	-
2		CRPF	Chennapur	11KV	Keesara	09.40	10.10	00.30		11KV HG Fuse failed near Dental College and 11KV line to line touched at Malkaram	-
3		RFC	UMARKHANGUDA	11KV	IBRAHIMPATNAM	08.30	09.30	01.00	EL/OL	11KV PIN INSULATOR FAIL AT TELEPHONE EXCHANGE GANDDICHERVU	-

TSSPDCL - LMRC / Corporate office

Date: 07.01.2018

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MDK	Habsipur	Raghothampally	33KV	Siddipet	04.05	11.30	07.25		BD due to Tree branches fallen on line	Habsipur	-
2		Kandhi	Isnapur	33KV	Sangareddy	06.00	12.30	06.30		BD due to Insulator failed	Kandhi	-