

**Status Report on Breakdowns (Urban / Rural)****Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	48	158									
2	NLG	18	406									
3	MDK	92	383									
4	RR(S)	40	201									
5	RR(N)	82	407									
6	RR(E)	38	360									
7	Hyd	186	1014									
	<b>Total</b>	<b>504</b>	<b>2929</b>	<b>0</b>	<b>0</b>	<b>0</b>	<b>0</b>	<b>0</b>	<b>0</b>	<b>0</b>	<b>0</b>	

**Rural**

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	110	969									
2	NLG	150	948	2	5	2	5	2	5			
3	MDK	87	828									
4	RR(S)	31	338									
5	RR(N)	8	48									
6	RR(E)	18	89									
	<b>Total</b>	<b>404</b>	<b>3220</b>	<b>2</b>	<b>5</b>	<b>2</b>	<b>5</b>	<b>2</b>	<b>5</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>908</b>	<b>6149</b>	<b>2</b>	<b>5</b>	<b>2</b>	<b>5</b>	<b>2</b>	<b>5</b>	<b>0</b>	<b>0</b>	

## TSSPDCL - LMRC / Corporate office

Date: 17.01.2018

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Edulur	Kurumarthy	11KV	Nalgonda	07.00	12.00	05.00	E/L	11KV Line Jumper Cut	-
2		Agamothkur	Chirumarthy	11KV	Mirylaguda	09.30	13.30	04.00	E/L	11KV conductor Snapped near Chirumarthy	-
3		Thungathurty	Ganugubanda	11KV	Suryapet	09.10	12.00	02.50	E/L	Jumper cut	-
4		Datharpally	Jangam Pally	11KV	Bhongir	04.15	09.00	04.45	E/L	11Kv Line snapped at Jangampally 3 Ph	-
5		Alingapuram	Alingapuram	11KV	Huzuragar	02.00	07.00	05.00	E/L	Due to 11Kv Jumper cutted	-

TSSPDCL - LMRC / Corporate office

Date: 17.01.2018

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	NLG	Ramapuram	Dondapadu	33KV	Huzurnagar	05.00	14.00	09.00		Due to 33kv Insulator failure and jumper cutted	Dondapadu	-
2		Haliya	Peddavoora	33KV	Mirylaguda	01.40	10.30	09.50		11KV Rural feeder leaned and touched 33KV pole near Anumula village	Peddavoora	-