

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234		1		1		1			
6	RR(N)	54	550	1	2	1	2	1	2			
7	RR(E)	168	403		3		3		3			
8	Hyd	194	1044									
	Total	606	3055	1	6	1	6	1	6	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1		1		1				
2	NLG	144	988	1	6	1	6	1	6			
3	MDK	107	933		1		1		1			
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	2	7	2	7	2	7	0	0	
	Grand Total	1082	6468	3	13	3	13	3	13	0	0	

TSSPDCL - LMRC / Corporate office

Date: 11.07.2018

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Kothur	Ennar	33KV	Shadnagar	19.52	23.35	03.43		R-Phase conductor snapped	Ennar	-
1	NLG	S.Gouraram	Nakrekal	33KV	Nalgonda	14.20	17.15	02.55	E/L	33 KV Insulator Failed	Ch.Annaram, Kadaparthi	-
1	RR N	132KV Medchal	33KV Nuthankal	33KV	Medchal	16.26	17.31	01.05	BD	Tree fallen on the 33KV Line at Medchal Checkpost	33KV Nuthankal	-

TSSPDCL - LMRC / Corporate office

Date: 11.07.2018

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Bollepally	Indiriyala	11KV	Bhongir	15.30	17.00	01.30	E/L	Heavy Gale & Wind 11kv Pin Insulator failed in near somla nayak well sureypally (v)	-
2		Sharjipet	Sharjipet	11KV	Bhongir	12.10	13.30	01.20	E/L	Heavy Gale & Wind 11kv line snpped near Thuppuguda(v)	-
3		Kudakuda	Komatikunta	11KV	Suryapet	12.10	15.15	03.05	E/L	11Kv Conductor snapped	-
4		Yerkaram	Das thanda	11KV	Suryapet	07.30	08.40	01.10	E/L	11Kv Insulator Failed	-
5		Keethavarigudem	Velidanda	11KV	Huzurnagar	09.35	14.35	05.00	E/L	11kv line snapped at Velidanda (v)	-
6		Kopple	Kopple	11KV	Nalgonda	12.46	14.28	01.42	E/L	11KV Line Insulator Failed	-
1	MDK	Bollaram-II	Vasagatta	11KV	Patancheru	14.25	16.25	02.00		B/D due to Conductor snapped.	-
1	RR S	Papireddy Colony	Market	11KV	GCB	19.25	20.25	01.00	BD	Out Going AB Switch Post off Insulator failed in Sub-Station	-
1	RR N	Medicity	IDA Medicity	11KV	Medchal	16.40	18.40	02.00	BD	11KV Disc and Pin Insulator failed at Medicity X Roads	-
2		Keshavaram	Uddamarry	11KV	Medchal	17.10	19.15	02.05	BD	11KV Disc failed at Keshavaram Village	-
1	RR E	Saketh	Saketh	11KV	SKP	09.15	09.50	00.35		Ground Petrolling done but no visible fault found (LM Malleth)	-
2		VP Nagar	VV Puram	11KV	SKP	10.00	10.30	00.30		Board fallen on 11Kv line at VV Puram Road No. 10 (LM Chanrda Sheker)	-
3		Moula-Ali	Gayathri Nagar	11KV	SKP	12.44	14.34	01.50		Car dashed on 11Kv line at Sadulla Nagar (Foc Raju)	-