

## Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550									
7	RR(E)	168	403		2		2		2			
8	Hyd	194	1044		1		1		1			
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>0</b>	<b>3</b>	<b>0</b>	<b>3</b>	<b>0</b>	<b>3</b>	<b>0</b>	<b>0</b>	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	2		2		2				
2	NLG	144	988	1	6	1	6	1	6			
3	MDK	107	933		6		6		6			
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>3</b>	<b>12</b>	<b>3</b>	<b>12</b>	<b>3</b>	<b>12</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>3</b>	<b>15</b>	<b>3</b>	<b>15</b>	<b>3</b>	<b>15</b>	<b>0</b>	<b>0</b>	

TSSPDCL - LMRC / Corporate office

Date: 13.07.2018

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Narayanapet	Narayanapet	33KV	Narayanapet	18.05	19.30	01.25	E/L	No Visible Fault	Narayanapet	NO
2		Nagarkurnool	lthole	33KV	Nagarkurnool	15.20	17.25	02.05		Due to Breaker Problem	Nagarkurnool	Alternate Supply Arranged From 33KV SS Nagarkurnool at 17:25Hrs
1	NLG	S.Gouraram	Nakrekal	33KV	Nalgonda	14.20	17.15	02.55		33 KV Insulator Failed	S.Gouraram	-

TSSPDCL - LMRC / Corporate office

Date: 13.07.2018

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Rajupeta	Jonnagaddla Gudem	11KV	Nalgonda	07.00	08.30	01.30	EL	11KV line Jumper Cut	-
2		Narketpally	Narketpally Town	11KV	Nalgonda	08.30	09.40	01.10	EL	11 KV Line Insulator Failed	-
3		Reddygudem	Kothagudem	11KV	Suryapet	11.10	13.15	02.05	EL	Conductor snapped	-
4		Garidepally	Ponugodu	11KV	Huzurnagar	14.30	17.30	03.00	EL	11 kv line snapped at Ponugodu village	-
5		Thogarrai	Kuchipudi	11KV	Huzurnagar	07.42	12.00	04.15	EL	11 kv inslater failed at Kuchipudi village	-
6		Akupamula	K K Gudem	11KV	Huzurnagar	02.30	05.30	03.00	EL	11 disk failed at K K Gudem village	-
1	MDK	SRD Town - I	New post office	11KV	Sangareddy	03.15	04.50	01.35		B/D Due to 11kv Conductor snapped near Mothimahal theater side	-
2		lkpet	Gowdicherla	11KV	Sangareddy	14.15	15.30	01.15		B/D Due to Insulator Failure	-
3		cheryal	kandi	11KV	Sangareddy	00.10	04.00	03.50		B/D Due to 11kv Conductor snapped at kingsdhaba	-
4		EPIP-II	Export	11KV	Sangareddy	10.26	11.00	00.34		B/D Due to Jumper Cut	-
5		Ismailkhan Pet 1x8	Indl	11KV	Sangareddy	10.20	11.20	01.00		B/D Due to Jumper Cut	-
6		Bollaram - II 2x8	Kottam	11KV	Sangareddy	13.00	14.20	01.20		B/D Due to Jumper Cut	-
1	RR E	CRPF	Chennapur	11KV	Keesara	01.05	02.25	01.20		Line patrolling but no visible fault	-
2		Parvathapur	Sathya Narayana Puram	11KV	Keesara	10.05	10.42	00.37		Lizard fallen on 11kv line at Sai Aishwarya Colony	-
1	HYD C	Industrial Area	V.S.T.	11KV	II	20.20	23.50	03.30	All Indication	Cable fault at Consumer side	-