

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		4		4		4			
7	RR(E)	168	403		3		3		3			
8	Hyd	194	1044		2		2		2			
	Total	606	3055	0	9	0	9	0	9	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849									
2	NLG	144	988		3		3		3			
3	MDK	107	933									
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	0	3	0	3	0	3	0	0	
	Grand Total	1082	6468	0	12	0	12	0	12	0	0	

TSSPDCL - LMRC / Corporate office

Date: 24.07.18

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Katanguru	Mallaram	11KV	Nalgonda	12:40	15:20	2:40		Jumper cut	No
2		Katanguru	Dugnevalli	11KV	Nalgonda	12.25	13.00	00.35		Insulator failed	No
3		Narketpally	Yellareddyguda	11KV	Nalgonda	14.00	16.55	02.55		AB Switch male female cut	No
1	RR N	Medchal	Kandlakoya	11KV	Saigeetha Asramam	3:09	3:29	0:20		Jumper cut	No
2		Medchal	Devarayamjal	11KV	DMC	11.20	13.15	01.55		Relay problem	No
3		Medchal	Shameerpet	11KV	Anthaipally	16.30	17.00	00.30		Cable fault	No
4		Medchal	Aliabad	11KV	Majeedpur	16.55	17.55	01.00		Conductor snapped	No
1	RR E	Keesara	Ankireddypally	11KV	Keesara	7:30	8:30	1:00		11KV Insulator failed in Keesara SS	No
2		Ghatkesar	Konadapur agl	11KV	Keesara	17:00	17:40	0:40		Tree branch fallen at Giddu krishna murthy college	No
3		RGK	RGK	11KV	Sainikpuri	12.00	12.45	00.45		11KV Side female clamp replaced	No
1	HYD S	Falaknuma	Chatrinaka	11KV	Charminar	04.00	06.40	02.40	EL	Breaker problem at SS (Protection wing inspected & feeder charged stood OK)	No
2		Arundhathi Colony	Kummarwadi	11KV	Asmangadh	15:00	16:25	1:25	EL,OL	AB Switch fire catch at Kummarwadi	No