

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550									
7	RR(E)	168	403									
8	Hyd	194	1044		2		2		2			
	Total	606	3055	0	2	0	2	0	2	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849									
2	NLG	144	988		8		8		8			
3	MDK	107	933		2		2		2			
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	0	10	0	10	0	10	0	0	
	Grand Total	1082	6468	0	12	0	12	0	12	0	0	

TSSPDCL - LMRC / Corporate office

Date: 29.07.2018

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Athmakur(S)	Dacharam	11kv	Suryapet	11.15	12.20	01.05	E/L	Bird fallen on the line	-
2		N B Gudem	Redlakunta	11kv	Huzurnagar	03.00	06.00	03.00	E/L	11 KV Jumper cut at Redlakunta village	-
3		Kodad	Town-2	11kv	Huzurnagar	23.15	00.40	01.25	E/L	11 KV LINE Snapped at Kodad town-2	-
4		Ananthagiri	Shantinagar	11kv	Huzurnagar	16.25	18.30	02.05	E/L	11 kv disk failed at Shantinagar village	-
5		Siripuram	Siripuram	11kv	Huzurnagar	11.30	13.30	02.00	E/L	11 KV Jumper cut at siripuram village	-
6		Kattangur	Bollepally	11kv	Nalgonda	09.15	15.45	06.30	E/L	11KV Line Insulator Fail	-
7		Pazzur	Peddasuraram	11kv	Nalgonda	10.50	13.50	03.00	E/L	AB Switch Femail Cutting	-
8		Thimmannagudem	Thelakantigudem	11kv	Nalgonda	11.20	16.20	05.00	E/L	11KV Line Cutting	-
1	MDK	Kistareddypet	Industrial	11kv	Patancheru	10.35	12.00	01.25		B/D Due to Conductor Snapped	-
2		Gaddapotharam -II	Agrobell	11kv	Patancheru	03.10	06.30	03.20		B/D Due to Jumper Cut	-
1	HYD C	Industrial Area	Shankermutt	11KV	II	02.20	03.40	01.20	EL,OL-Rph	No Visible Fault	-
2	HYD S	Asmangadh	Shiva Ganga	11KV	VIII	17.27	19.15	01.48	EL	Pin Insulator flash over at Gaddi Annaram X Roads	-

TSSPDCL - LMRC / Corporate office

Date: 29.07.2018

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR				NIL							-
2	NLG				NIL							-
3	MDK				NIL							-
4	SDPT				NIL							-
5	RR S				NIL							-
6	RR N				NIL							-
7	RR E				NIL							-
8	HYD				NIL							-