

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		1		1		1			
7	RR(E)	168	403									
8	Hyd	194	1044	1	2	1	2	1	2			
	Total	606	3055	1	3	1	3	1	3	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849									
2	NLG	144	988		6		6		6			
3	MDK	107	933	1	1	1	1	1	1			
4	SDPT				3		3		3			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	1	10	1	10	1	10	0	0	
	Grand Total	1082	6468	2	13	2	13	2	13	0	0	

TSSPDCL - LMRC / Corporate office

Date: 20.06.2018

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MDK	Jogipet	Laxmi sagar	33KV	Jogipet	15.30	17.50	02.20		BD due to Pin Insulator failed	Laxmi sagar	-
1	HYD N	132KV Patigadda	Sanjeevaiah Park	33KV	Nehru Ngr	01.18	01.30	00.12	EL,OL	Cable damaged by R&B Staff	Sanjeevaiah Park	Loads transferred onto 132KV Gunrock SS - 33KV Airport SS

TSSPDCL - LMRC / Corporate office

Date: 20.06.2018

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Dirsenpally	Yerrapahad	11KV	Suryapet	14.00	15.30	01.30	E/L	Jumper cut	-
2		Shuvanagudem	R.R.Pally	11KV	Devarakonda	06.50	11.45	04.55	E/L	11 KV Insulator Failed	-
3		Shuvanagudem	S.R.Guda	11KV	Devarakonda	13.18	14.03	00.45	E/L	Tree Follen the Line	-
4		Dirincherla	Dirincherla	11KV	Huzurnagar	13.00	15.30	02.30	E/L	AGL Lines cutting at Dirincherla village	-
5		Dirincherla	Somaram	11KV	Huzurnagar	08.40	10.40	02.00	E/L	11 kv line snapped at Somaram village	-
6		Kandibanda	Yarraram	11KV	Huzurnagar	12.50	14.20	01.30	EL	Brekar problem in Kandibanda ss	-
1	MDK	Bollaram-I	Vipla	11KV	Sangareddy	10.55	12.05	01.10		BD due to Insulator failed	-
1	SDP	HUSNABAD	VUTLAPALLI	11KV	Siddipet	14.20	16.00	01.40		B/D No visible fault	-
2		SHANIGARAM	GUNDAREDDY PALLI	11KV	Siddipet	17.30	18.20	00.50		B/D due to heavy rain	-
3		GURUVANNAPETA	POSANPALLI	11KV	Siddipet	02.30	09.30	07.00		B/D Line snapped	-
1	RR N	Kompally	Jaibheri	11KV	Medchal	01.20	02.15	00.55	BD	11KV Pin Insulator Failed at Nagarjuna Dream Lands	-
1	HYD N	Muffakamja College	Amrutha	11KV	X	02.09	03.35	01.26	EL,OL	No Visible Fault	Arranged B/F on 11KV Road No.14 feeder
1	HYD S	Laxmi Nagar	Vinay Nagar	11KV	VIII	16.05	17.15	01.10	EL,OL-Yph	No Visible Fault	R.R.bit AB switch opened at Bharath Garden (17:20Hrs full fdr charged)