

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	RR(S)	53	234									
5	RR(N)	54	550		1		1		1			
6	RR(E)	168	403									
7	Hyd	194	1044		1		1		1			
	Total	606	3055	0	2	0	2	0	2	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849									
2	NLG	144	988		4		4		4			
3	MDK	107	933									
4	RR(S)	58	396									
5	RR(N)	38	114									
6	RR(E)	22	133									
	Total	476	3413	0	4	0	4	0	4	0	0	
	Grand Total	1082	6468	0	6	0	6	0	6	0	0	

TSSPDCL - LMRC / Corporate office

Date: 30.02.2018

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Cheedella	Chetla Mukundapuram	11KV	Suryapet	08.40	11.00	02.20	EL	Bird Fallen on the line	-
2		Gattupal	Theratipally	11KV	Nalagonda	16.00	18.00	02.00	EL	11KV Line Jumper Cutt	-
3		Damaracherla	Damaracherla AGL	11KV	Miryalaguda	07.30	10.30	03.00	EL	11KV Line Jumper Cutt	-
4		Neredugommu	Neredugommu	11KV	Devarakonda	05.00	07.30	02.30	EL	Insulator failure	-
1	RR N	Madinaguda	JPN Nagar	1KV	Kukatpally	14.06	15.21	01.15	EL	11KV line 11 insulator failure at TDFC bank back side	-
1	HYD S	Asmangadh	G.A.Bank Colony	11KV	VIII	01.05	02.20	01.15	EL	No Visible Fault	Arranged B/F on 11KV Tirumala Hills & Gowtham Ngr feeders

