

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234	1		1		1				
6	RR(N)	54	550		1		1		1			
7	RR(E)	168	403									
8	Hyd	194	1044	1	1	1	1	1	1			
	Total	606	3055	2	2	2	2	2	2	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849									
2	NLG	144	988	1	4	1	4	1	4			
3	MDK	107	933	2	1	2	1	2	1			
4	SDPT				2		2		2			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	3	7	3	7	3	7	0	0	
	Grand Total	1082	6468	5	9	5	9	5	9	0	0	

TSSPDCL - LMRC / Corporate office

Date: 11.05.18

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	NLG	Thungathurty	Annaram	33KV	Suryapet	02.50	06.10	03.20	E/L	Insulator flashed over	Annaram	No
1	MDK	Chegunta	Chegunta	33KV	Toopran	18:20	20:25	2:05		Tree branches fallen on the line near Pedda Shivanoor (V)	Chegunta	No
2		Chegunta	Yeldurthi	33KV	Toopran	18.10	20.35	02.25		Pin Insulator failed near Suraram (V)	Yeldurthi	No
1	RR S	Ibrahimpattam	Eliminedu	33KV	Ibrahimpattam	9:12	10:45	1:33		conductor snapped at Brundavan colony, Ibrahimpattam	Eliminedu	No
1	HYD N	132KV Erragadda	H.P.S (Idle)	33KV	Allwyn	01.30	16.10	14.40	EL,OL	Cable fault near Andhra Bank ATM, A.G Colony	H.P.S (Idle)	No

TSSPDCL - LMRC / Corporate office

Date: 11.05.18

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Penpahad	Macharam	11KV	Suryapet	7:30	10:00	2:30	E/L	Conductor snapped	No
2		Chervupally	Dacharam	11KV	Nalgonda	05.30	11.50	06.20	E/L	11KV Insulator failed	No
3		Angadipeta	Chilkamarri	11KV	Devarakonda	08.00	11.00	03.00	E/L	Conductor Sanpped	No
4		Ghanapuram	Polkampally	11KV	Devarakonda	07.30	10.15	02.45	E/L	Conductor Sanpped	No
1	MDK	SRD T-1	Fasalwadi	11KV	Sangareddy	8:16	10:40	2:24		Conductor Snapped	No
1	SDPT	Pullur	Pullur	11KV	Siddipet	19:30	6:35	11:05		Tree branch fallen on the 11KV line	No
2		Jakkapur	Shanigakunta	11KV	Siddipet	5:30	12:06	6:36		Pole Damaged road side due to vehcle dashed	No
1	RR N	ICICI	SP-I	11KV	Medchal	18:20	19:08	0:48		11KV UG Cable failed at 900 Company	No
1	HYD C	Industrial Area	Mother Dairy	11KV	Azamabad	19.25	20.50	01.25	EL	No Visible Fault	No