

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234		1		1		1			
6	RR(N)	54	550									
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044	1		1		1				
	Total	606	3055	1	2	1	2	1	2	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1		1				1		1 No. 33kv still
2	NLG	144	988		6		6		6			
3	MDK	107	933									
4	SDPT				10		10		10			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	1	16	1	16	0	16	1	0	
	Grand Total	1082	6468	2	18	2	18	1	18	1	0	

TSSPDCL - LMRC / Corporate office

Date: 18.11.2018

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Akaram	Vaddipamula	11kv	Nalgonda	10.00	11.30	01.30	EL	11KV Line insulator failed	-
2		Thatipamula	Nandhapuram	11kv	Suryapet	08.20	11.00	02.40	EL	Insulator flashover	-
3		Dirsincherla	Dirsincherla	11kv	Huzurnagar	09.00	11.20	02.20	EL	Due to tree Branch fall on 11kv line	-
4		Dirsincherla	Yellapuram	11kv	Huzurnagar	07.30	10.00	02.30	EL	Due to 11Kv jumper Cutted	-
5		B.N.Thanda	Vardapuram	11kv	Huzurnagar	05.30	07.00	01.30	EL	Due to 11Kv jumper Cutted	-
6		Mattampally	Ramchandrapuram	11kv	Huzurnagar	16.55	18.20	01.25	EL	Due to 11Kv jumper Cutted	-
1	SDPT	Koheda	Venkateshwarapally	11kv	Husnabad	11.50	12.30	00.40		BD Due to jumper cut	-
2		Komuravelly	Inapur	11kv	Husnabad	01.50	13.10	11.20		BD Due to rain	-
3		Gouravelly	Gubbadi Jangam	11kv	Husnabad	00.30	06.30	06.00		BD Due to DTR problem	
4		Dharmaram	Nandaram	11kv	Husnabad	08.20	08.40	00.20		BD Due to HG fuse problem	
5		Akunoor	Rampoor	11kv	Husnabad	03.05	18.10	15.05		BD Due to conductor snapped	
6		Mustyal	Cherial Agl	11kv	Husnabad	12.10	13.55	01.45		BD(3Ph) Due to rain,1Ph ok	
7		Nagapuri	Nagapuri	11kv	Husnabad	00.00	07.27	07.27		BD Due to conductor snapped	-
8		Nagapuri	Gandikunta	11kv	Husnabad	00.45	07.28	06.43		BD Due to conductor snapped	-
9		Nagapuri	Pothireddypalli	11kv	Husnabad	00.00	06.00	06.00		BD Due to conductor snapped	-
10		Chityal	Chityal 24 Hrs	11kv	Husnabad	08.45	10.45	02.00		BD Due to jumper cut	-
1	RR S	Kismathpur	LV Prasad	11kv	RJNR	11.30	13.00	01.30	B/D	Breaker fault, B/F Given on 11KV Difence colony	-
1	RR E	VP Nagar	Brundhavan Colony	11kv	Sainikpuri	14.01	14.47	00.46		Bird fallen on 11Kv line GK Colony Batia T/F (AE/OP)	-

TSSPDCL - LMRC / Corporate office

Date: 18.11.2018

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Gadwal	Bijwaram	33kv	Gadwal	23.20	00.00	00.40	E/L&O/L	Break Down Due to Pin Binding Failure at 132KV SS Back Side Fast Pole (Not Rectified)	Bijwaram	-
1	HYD N	132KV Erragadda	Yellareddyguda	33kv	Erragadda	03.45	03.55	00.10	EL,OL	Old Straight through Joint Kit failed near 33/11KV Yellareddyguda SS	Yellareddyguda	Loads transferred onto 132KV Erragadda SS via 33KV Sri Nagar Colony for