

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		2		2		2			
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044		2		2		2			
	Total	606	3055	0	5	0	5	0	5	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1		1		1				
2	NLG	144	988									
3	MDK	107	933									
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	1	0	1	0	1	0	0	0	
	Grand Total	1082	6468	1	5	1	5	1	5	0	0	

TSSPDCL - LMRC / Corporate office

Date: 13.10.2018

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Marikal	Kokuntla	33KV	Mahabubnagar	16.05	21.50	05.45	O/L	for 33 KV Jumper cut at 132KV Marikal SS	Marikal	No

TSSPDCL - LMRC / Corporate office

Date: 13.10.2018

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	RR N	Jeedimetla-I	Su Drugs	11KV	Jeedimetla	17.15	20.30	03.15	EL/OL	11kv Jumper Cut At Sai kanta Phase-I	-
2		Kandlakoya	Kandlakoya	11KV	Medchal	06.10	09.40	03.30		11KV Box Pole damaged by Lorry and replaced at Ultratech cement company,Kandlakoya	-
1	RR E	Uppal	Bankcolony	11KV	Habsiguda	09.45	10.45	01.00		11kv jumper cut in SS yard	-
1	HYD S	Miralam	MCH Colony	11KV	Charminar	21.55	23.20	01.25	EL	Incoming Cable failed & Pin Insulator flash over at Govt.School backside, Teegalakunta	-
2		E.N.T	C.B.I	11KV	Bebumbazar	22.45	23.59	01.14	All Indicaion	Breaker fault at SS	-