

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234		1		1		1			
6	RR(N)	54	550		4		4		4			
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044		1		1		1			
	Total	606	3055	0	7	0	7	0	7	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849		1		1		1			
2	NLG	144	988		6		6		6			
3	MDK	107	933		2		2		2			
4	SDPT				5		5		5			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	0	14	0	14	0	14	0	0	
	Grand Total	1082	6468	0	21	0	21	0	21	0	0	

TSSPDCL - LMRC / Corporate office

Date: 27.10.2018

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Kaverammamet	Bandamidipally	11KV	Jadcherla	11.05	14.05	03.00		AB Switch Problem Near Bandamidipally	-
1	NLG	Nuthankal	Yerrapahad	11KV	Suryapet	06.45	09.10	02.25	E/L	11Kv Conductor snapped	-
2		N B Gudem	Redlakunta	11KV	Huzurnagar	05.40	07.20	01.40	E/L	100KVA Transformer problem	-
3		Eduloor	Garlabaigudem	11KV	Nalgonda	04.00	07.00	03.00	E/L	11KV jumper cut at SS-16	-
4		Madanapuram	Kurmed	11KV	Devarakonda	14.15	16.20	02.05	O/L	HT/HT	-
5		Teeded	GajiramThanda	11KV	Devarakonda	15.00	16.33	01.33	E/L	11Kv Jumper Cut	-
6		A.D.Pally	Veerlapalem	11KV	Miryalguda	03.05	07.45	04.40	E/L	11KV conductor snaped	-
1	MDK	Medikunda	Gorekal	11KV	Jogipet	10.00	13.00	3:00		B/D due to Conductor Snapped near Gorekal(V)	-
2		Hanmanthrapet	Ananthasagar	11KV	Jogipet	11.00	14.00	3:00		B/D due to Pin Insulator failure near Ananthasagar(V)	-
1	SDPT	Peddakodur	Peddakodur Townn	11KV	SDPT	09.45	11.45	02.00		LC for Bill Collection	-
2		Dubbak	Dubbak Town	11KV	SDPT	12.00	12.20	00.20		LC for Bill Collection	-
3		Akkannapet	Pakilnayak Thanda	11KV	SDPT	07.15	11.45	04.30		11KV condutor snapped	-
4		Baswapur	Baswapur (R)	11KV	SDPT	01.20	07.20	06.00		Insulator Failure	-
5		Bekkal	Thornala	11KV	SDPT	09.10	10.10	01.00		11KV condutor snapped	-
1	RR S	Kokapet	Akshayapatra	11KV	IBGH	12.58	14.54	01.56	EL/OL	11kv Pole broken at shanthi nagar Due To Tipper Lorry Dashed	-
1	RR N	Suraram	Matrix	11KV	Jeedimetla	08.10	10.05	01.55	EL	11kv AB Cable Failure At Mylon Company Phase--IV	-
2		Jeedimetla -V	S S industrie	11KV	Jeedimetla	08.10	10.20	02.10	EL/OL	11kv AB Cable Failure At Mylon Company Phase--IV	-
3		Athiwelly	PHI	11KV	Medchal	12.30	15.30	03.00		11KV Pin Insulator failed at Yellampet SS Backside	-
4		Kistapur	IDA Hanuman	11KV	Medchal	15.35	16.10	00.35		Bird fallen on the 11KV Line at Bricks Company	-
1	RR E	Kushaiguda	Neredmet	11KV	Sainikpuri	13.20	14.20	01.00		Tree branches fallen on 11Kv line at AS Rao Nagar (AE/OP)	-
1	HYD N	R.P Nilayam	Naga Devatha Temple	11KV	Sec'bad	07.30	09.00	01.30	EL	CT PT fault at H.E.L, Military Area	

TSSPDCL - LMRC / Corporate office

Date: 27.10.2018

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBN				NIL							-
2	NLG				NIL							-
3	MDK				NIL							-
4	SDPT				NIL							-
5	RR S				NIL							-
6	RR E				NIL							-
7	RR N				NIL							-
8	HYD				NIL							-