

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550	2		2		2				
7	RR(E)	168	403									
8	Hyd	194	1044		1		1		1			
	Total	606	3055	2	1	2	1	2	1	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1		1		1				
2	NLG	144	988		5		5		5			
3	MDK	107	933	1		1						
4	SDPT				2		2		2			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	2	7	2	7	1	7	0	0	
	Grand Total	1082	6468	4	8	4	8	3	8	0	0	

TSSPDCL - LMRC / Corporate office

Date: 28.10.2018

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Eduloor	G.B.Gudem	11KV	Nalgonda	06.00	10.00	04.00	E/L	11KV Line cut	-
2		Eduloor	Parada	11KV	Nalgonda	14.00	17.00	03.00	E/L	11KV Jumper cut	-
3		N.B.Gudem	Redlakunta	11KV	Huzurnagar	04.00	07.00	03.00	E/L	11KV Jumper cut	-
4		Repala	Narsimhulagudem	11KV	Huzurnagar	06.15	08.30	02.15	E/L	11KV Insulator failure	-
5		Palakeedu	Guduguntlapalem	11KV	Huzurnagar	16.30	18.00	01.30	E/L	11KV Disk failed	-
1	SDPT	Shanigaram	Thangalapally	11KV	SDPT	13.10	14.00	00.50		Jumper cutting	-
2		Baswapur	Baswapur	11KV	SDPT	00.00	06.50	06.50		Jumper cutting	-
1	HYD S	Miralam	Mustafa Nagar	11KV	Charminar	16.00	17.15	01.15	EL,OL	2No. Conductors snapped at Mahamoodiya Masjid	-

TSSPDCL - LMRC / Corporate office

Date: 28.10.2018

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Makthal	Narva	33KV	Narayanapet	14.10	19.20	05.10		Pin banding work Near Khanapur Lift	Narva	-
1	MDK	Pashamailaram	EPIP II	33KV	Sangareddy	14.40	18.40	04.00		BD Due Jumper Snapped at 132 KV Pashamailaram SS	EPIP II	-
1	RR N	132KV Medchal	33KV Athiwelly	33KV	Medchal	20.00	20.45	00.45		33KV Cable Fault backfeeding arranged from 33KV Nuthankal Feeder(132KV Medchal SS)	33KV Athiwelly	-
2		132KV Medchal	33KV Devarayamjal	33KV	Medchal	17.13	17.40	00.27		33KV Cable Fault backfeeding backfeeding arranged from 33KV Rathnalayam Feeder	33KV Devarayamjal	-