

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234		1		1		1			
6	RR(N)	54	550									
7	RR(E)	168	403									
8	Hyd	194	1044									
	Total	606	3055	0	1	0	1	0	1	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1		1		1				
2	NLG	144	988	1	2	1	2	1	2			
3	MDK	107	933	3	2	3	2	3	2			
4	SDPT			2	9	2	9	2	9			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	7	13	7	13	7	13	0	0	
	Grand Total	1082	6468	7	14	7	14	7	14	0	0	

TSSPDCL - LMRC / Corporate office

Date: 29.10.2018

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Nakkalapally	Shapally	11KV	Nalgonda	11.30	14.10	02.40	EL	Tree fallen on 11 KV line	-
2		SLBC	M.D.Pally	11KV	Nalgonda	08.05	10.30	02.25	EL	11KV Line Cut	-
1	MDK	Nandigama	Vishaka	11KV	Sangareddy	07.10	08.10	01.00		B/D Due to Insulator failure	-
2		Nanigama	Fennoplast	11KV	Sangareddy	11.00	12.00	01.00		B/D Due to Conductor Snapped	-
1	SDPT	Akkannapet	Akkannapet Rural	11KV	Husnabad	11.40	16.40	05.00		Tree brach fallen on line, same rectified	-
2		Thotapally	Veerapur	11KV	Husnabad	11.50	17.50	06.00		Conductor snapped, same rectified	-
3		Mustyal	Veerannapet	11KV	Husnabad	12.20	15.50	03.30		Tree brach fallen on line, same rectified	-
4		Komuravelly	Peddarajupeta	11KV	Husnabad	09.45	12.15	02.30		Insulator fail same rectified.	-
5		Komuravelly	Inapur Agl	11KV	Husnabad	13.15	17.30	04.15		Insulator fail same rectified.	-
6		Katkur	Katkur Rural	11KV	Husnabad	13.20	14.50	01.30		Insulator fail same rectified.	-
7		Katkur	Mallaram	11KV	Husnabad	20.05	23.50	03.45		Insulator fail same rectified.	-
8		Chityal	Thadoor	11KV	Husnabad	12.55	13.15	00.20		Gale and wind	-
9		Dhoolmitta	Lingapur	11KV	Husnabad	11.20	12.25	01.05		Tree brach fallen on line, same rectified	-
1	RR S	ESCI	Nanakramguda	11KV	Gachibowli	12.40	14.30	01.50		UG Cable Damaged in Divya Sree	-

TSSPDCL - LMRC / Corporate office

Date: 29.10.2018

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Gadwal	Nandinne	33KV	Gadwal	01.10	05.10	04.00	O/L	Line Phase to Phase near 132KV SS		Alternate Supply Arranged From RWS SS at 05:10Hrs.
1	NLG	Aitipamula	Aitipamula	33KV	Nalgonda	11.44	13.15	01.31	EL	Jumpet Cut		-
1	MDK	Narayankhed	Sirgapur	33KV	Jogipet	11.10	18.10	07.00		B/D Due to Insulator failure and Jumper Cut		-
2		Zaheerabad	Machanoor	33KV	Zaheerabad	14.35	15.20	00.45		B/D Due to Jumper Cut		-
3		Sadasivpet	Koheer	33KV	Sangareddy	15.30	16.10	00.40		B/D Due to Conductor Snapped		-
1	SDPT	Angadi kistapur	Jagadevpur	33KV	Gajwel	12.05	13.55	01.50		Insulator Pin Bend		
2		Siddipet	Mittapally	33KV	Siddipet	10.50	11.20	00.30		Line Faut		