

## Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234	1		1		1				
6	RR(N)	54	550	1		1		1				
7	RR(E)	168	403		2		2		2			
8	Hyd	194	1044									
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>2</b>	<b>2</b>	<b>2</b>	<b>2</b>	<b>2</b>	<b>2</b>	<b>0</b>	<b>0</b>	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	3	2	3	2	3	2			
2	NLG	144	988		5		5		5			
3	MDK	107	933									
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>3</b>	<b>7</b>	<b>3</b>	<b>7</b>	<b>3</b>	<b>7</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>5</b>	<b>9</b>	<b>5</b>	<b>9</b>	<b>5</b>	<b>9</b>	<b>0</b>	<b>0</b>	

TSSPDCL - LMRC / Corporate office

Date: 28.09.2018

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Kothamolgara	Kothamolgara	11KV	Jadcherla	12.40	15.50	03.10		11KV Insulator fail near Ravulapalem (Vi).	-
2		Balanagar	Nerellapally	11KV	Jadcherla	22.34	08.48	10.14		11 Kv Disc failure near Mamidigutta tanda Side.	-
1	NLG	B.Chandupatla	Thimmapuram	11KV	Suryapeta	08.30	10.45	02.15	E/L	Disc flashover	-
2		Mukundapuram	Mukundapura	11KV	Huzurnagar	07.05	10.05	03.00	E/L	11KV Jumper cut	-
3		Repala	V.R.Puram	11KV	Huzurnagar	15.45	18.40	02.55	E/L	11KV Jumper cut	-
4		Chamapur	Singaram	11KV	Bhongiri	12.00	16.10	04.10	E/L	11KV Insulator failure	-
5		Solipeta	Ramuluthanda	11KV	Bhongiri	15.00	16.00	01.00	E/L	11KV Insulator failure	-
1	RR E	CRPF	Chennapur	11KV	Keesara	15.55	17.35	01.40		Line Patrolling but no visible fault	-
2		Balaji Nagar	Mahankali	11KV	Keesara	13.32	18.22	04.50		11KV UG Cable cut at SS Yard	-

TSSPDCL - LMRC / Corporate office

Date: 28.09.2018

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Marikal	Koukuntla	33KV	Mahabubnagar	13.58	16.20	02.22		No Visible Fault		No
2		Wanaparthy	Chinnamaroor	33KV	Wanaparthy	11.15	11.30	00.15	E/L	No Visible Fault		Alternate Supply Arranged From 33KV Pebbair at 11:30Hrs.
3		Amarchintha	Atmakur	33KV	Wanaparthy	14.54	14.55	00.01	E/L	Pin Insulator Replaced near Amarchintha		Alternate Supply Arranged From 33KV Amarchinta at 14:55Hrs.
1	RR S	220kv Shamshabad	33kv Shamshabad-SHBD	33KV	RJNR	01.38	12.25	10.47	B/D	33KV Pole Damaged at Ammapally Temple Narkuda due to Car dashed B/F arranged to 11KV feeders		-
1	RR N	132KV LGM Pet	33KV Aliabad	33KV	Medchal	13.55	15.15	01.20		Tree fallen on the 33KV Line at Pitla Narasimha Lane, Aliabad		-