

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No. of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550									
7	RR(E)	168	403									
8	Hyd	194	1044	1	2	1	2	1	2			
	Total	606	3055	1	2	1	2	1	2	0	0	

Rural

S.No	Circle	No. of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1		1		1				
2	NLG	144	988	1	7	1	7	1	7			
3	MDK	107	933		1		1		1			
4	SDPT			1		1		1				
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	3	8	3	8	3	8	0	0	
	Grand Total	1082	6468	4	10	4	10	4	10	0	0	

TSSPDCL - LMRC / Corporate office

Date: 15.04.2019

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Polkonda	Jananpet	33KV	Mahabubnagar	01.50	02.46	00.56	E/L	AB Switch Open at Seeds Company	Jananpet	-
1	NLG	Wadapally	Janpahad	11KV	Huzurnagar	11.40	13.00	01.20		Line snapped	Janpahad	-
1	SDP	Chandlapur	Kamarlapally	33KV	Siddipet	17.00	17.58	00.58		Tower Break	Kamarlapally	-
1	HYD S	220KV Ch' Gutta	Arundathi Colony	33KV	Malakpet	14.53	15.00	00.07	EL,OL-Bph	Cable damaged near DRDL by HMWS	Arundathi Colony	Loads transferred onto 220KV Ch' Gutta SS via 33KV CRPF fdr

TSSPDCL - LMRC / Corporate office

Date: 15.04.2019

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Kasarabad	Express Feeder	11KV	Suryapet	14.15	16.20	02.05		Insulator failure	-
2		Palakidu	Bothapalem	11KV	Huzurnagar	07.00	09.30	02.30		Line snapped	-
3		Ragunathpalem	Nakkagudem	11KV	Huzurnagar	12.00	13.30	01.30		Jumper cut	-
4		Kodada Indore	Komarabanda Indl	11KV	Huzurnagar	14.50	17.10	02.20		Insulator failure	-
5		Chervupally	Dacharam	11KV	Nalgonda	12.00	14.00	02.00		Line AB Switch Jumper cut	-
6		Pallem	Ogodu	11KV	Nalgonda	05.00	07.40	02.40		Line snapped	-
7		Akaram	Shanathanagar	11KV	Nalgonda	04.00	08.00	04.00		Insulator failure	-
1	MDK	Cheryal	Indrakaran	11KV	Sangareddy	08.45	12.00	03.15		B/D Due to Jumper Cut	-
1	HYD N	Prasasan Nagar	B.N.R Hills	11KV	X	03.20	04.50	01.30	EL, OL	HT Conductor snapped at Road No.51	-
2		Gymkhana	Pared Ground	11KV	V	08.31	09.41	01.10	EL,OL-Rph	Breaker problem at SS	Arranged B/F on 11KV J.B.S feeder