

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No. of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550									
7	RR(E)	168	403									
8	Hyd	194	1044		2		2		2			
	Total	606	3055	0	2	0	2	0	2	0	0	

Rural

S.No	Circle	No. of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	2		2		2				
2	NLG	144	988	1	7	1	7	1	7			
3	MDK	107	933									
4	SDPT				4		4		4			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	3	11	3	11	3	11	0	0	
	Grand Total	1082	6468	3	13	3	13	3	13	0	0	

TSSPDCL - LMRC / Corporate office

Date: 29.04.2019

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Maddur	Maddur	33KV	Narayanapet	15.15	16.44	01.29	E/L	Condcutor Touched to Crossaram	Maddur	-
2		Maddur	Vepoor	33KV	Narayanapet	16.15	20.00	03.45	O/L	33KV Line Phase to Phase and Tree Fallen on the Line	Vepoor	Alternate Supply Arranged to 33KV Kothapally Feeder at 20:00Hrs Vepoor Feeder Idel Charged)
1	NLG	Mattampally	Raghunadhapalem	33KV	Huzurnagar	05.30	08.30	03.00	EL	Due to 33KV Insulator failure	Raghunadhapalem	-

TSSPDCL - LMRC / Corporate office

Date: 29.04.2019

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Gondriyala	Gondriyala 01	11KV	Huzurnagar	10.05	13.00	02.55	EL	Due to 11Kv jumper cutted	-
2		Ananthagiri	Mogalaikota	11KV	Huzurnagar	04.15	07.00	02.45	EL	Due to 11Kv jumper cutted	-
3		Sirikonda	Balluthanda	11KV	Huzurnagar	23.00	01.00	02.00	EL	Due to 11Kv jumper cutted	-
4		Arlagaddagudem	Suraram	11KV	Nalgonda	06.00	08.10	02.10	EL	11 KV Disc Failure	-
5		Akaram	Shanthinagar	11KV	Nalgonda	14.12	16.10	01.58	EL	11 KV Line Jumper Cut	-
6		Kanagal	Lachugudem	11KV	Nalgonda	09.40	12.05	02.25	EL	HT/LT Lines Melt	-
7		Velmajala	Seetharampur	11KV	Bhongiri	06.35	08.05	01.30	EL	Bird Fallen at Line Chippalakunta, Near Seetharampur Village.	-
1	SDP	Gouravelly	Gubbadi Jangam	11KV	Husnabad	03.25	05.30	02.05		3 Ph BD,1 Ph ok, Due to conductor short	-
2		Pandilla	Pandilla Rural	11KV	Husnabad	06.20	08.10	01.50		BD, Due to conductor snapped	-
3		Potharam	Potharam Town	11KV	Husnabad	15.50	19.00	03.10		BD, Due to conductor snapped	-
4		Mustyal	Veerannapet	11KV	Husnabad	00.40	01.20	00.40		BD, Due to gale & wind	-
1	HYD N	I.I.C.T	Dall Mill	11KV	V	02.45	03.55	01.10	EL	Pin Insulator flash over at Nagarjuna Nagar Community Hall	-
1	HYD S	Devi Bagh	Edgah	11KV	III	21.16	22.25	01.09	EL	AB Switch Jumper cut at Zoo Park	-