



## TSSPDCL - LMRC / Corporate office

Date: 09.02.2019

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Karkonda	Khanapur	11kv	Jadcherla	09.40	11.37	01.57		11KV Jumper cut Near Khanapur	-
1	NLG	Kethepally	Inupamula	11kv	Nalgonda	06.30	12.10	05.40	E/L	11KV line Cutting	-
2		Nakirekal	Marrur	11kv	Nalgonda	09.30	11.40	02.10	E/L	11KV Insulator Failure	-
3		Thungathurthy	Ganugubanda	11kv	Suryapet	08.20	11.00	02.40	E/L	Insulato flashvoer	-
4		Mukundapuram	Dacharam	11kv	Huzurnagar	13.14	15.55	02.41	EL	Due to bird fall on on 11kv line	-
5		Munagala	Bharakath Gudem	11kv	Huzurnagar	12.11	13.16	01.05	OL	Due to tree branch fall on 11kv line	-
6		Repala	Kalakova	11kv	Huzurnagar	04.30	08.00	03.30	EL	Due to tree branch fall on 11kv line	-
7		Kolanpaka	Raghavapur	11kv	Bhongir	04.30	10.55	06.25	EL	11kvPin Insulator Fail	-
8		Alair	Ch.Kandukur	11kv	Bhongir	13.30	14.40	01.10	EL	11kv Disc Fail	-

TSSPDCL - LMRC / Corporate office

Date: 09.02.2019

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Mahabubnagar	SVS Eidra	33kv	Mahabubnagar	11.25	12.20	00.55	E/L	Pin insulator replaced near by SVS SS Hospital	SVS Eidra	-
1	SDPT	Chandlapur	Kammarlapally	33kv	Siddipet	08.22	11.50	03.28		EL tripped and Tree cutting	Kammarlapally	-