

TSSPDCL - LMRC / Corporate office

Date: 15.02.2019

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Gundlapotlapally	Kallepally	11kv	Jadcherla	09.00	12.00	03.00		Psase to Phase Near Kallepally(V)	-
1	NLG	Janpahad	Janpahad	11kv	Huzurnagar	02.30	05.30	03.00	E/L	11Kv line snapped	-
2		Nelamarry	V.R.Puram	11kv	Huzurnagar	13.45	15.45	02.00	O/L	Tree branch fall on 11Kv line	-
3		G T Giri	G T Giri	11kv	Suryapet	06.25	08.20	01.55	E/L	HT/LT line melt	-
4		Arlagaddagudem	Mangalapally	11kv	Nalgonda	09.30	11.40	02.10	E/L	11KV jumper cut	-
5		Gudapoor	Ukondi	11kv	Nalgonda	11.36	12.40	01.04	E/L	11KV jumper cut	-
6		Chandupatla	Indl	11kv	Bhongir	05.10	08.30	03.20	O/L	11KV Pole Dammaged & 11kv Line Snapped Damber plant Near Chimalakondur Village	-
7		MT.Pally	Dharmaram	11kv	Bhongir	09.25	11.15	01.50	O/L	SS-15 Jumper Cut Maisamma Temple Near Malkapur Village	-
1	SDPT	Bejjanki	Kallepally	11kv	SDPT	16.20	18.00	01.40		11Kv line snapped	-

TSSPDCL - LMRC / Corporate office

Date: 15.02.2019

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MDK	Kandi	XL RUBBER	33kv	Sangareddy	11.05	12.15	01.10		BD due to tree fallen on line	XL RUBBER	-
2		Zaheerabad	Machanoor	33kv	Zaheerabad	11.30	15.00	03.30		BD due to Insulator failed	Machanoor	-
3	SDPT	Gajwel	Pragnapur	33kv	Gajwel	10.55	13.15	02.20		B face Genpar out from Clamp	Pragnapur	-
1	RR N	132KV LGM Pet	33KV BE Vaccine	33KV	Medchal	11.23	13.06	01.43		33KV Pin Insulator failed at Nectar Company	33KV BE Vaccine	-