

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No. of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550									
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044		2		2		2			
	Total	606	3055	0	3	0	3	0	3	0	0	

Rural

S.No	Circle	No. of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849		1		1		1			
2	NLG	144	988		7		7		7			
3	MDK	107	933		1		1		1			
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	0	9	0	9	0	9	0	0	
	Grand Total	1082	6468	0	12	0	12	0	12	0	0	

TSSPDCL - LMRC / Corporate office

Date: 17.01.2019

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Midjil	Munnanoor	11KV	Jadcherla	08.30	13.30	05.00		11KV Wire cut near Munnanoor	-
1	NLG	Athmakur(S)	T Penpahad	11KV	Suryapet	12.50	14.10	01.20	EL	Jumper cut	-
2		Nadigudem	Ratnavaram	11KV	Huzurnagar	02.30	05.30	03.00	EL	Due to 11Kv jumper cutted	-
3		N.B.Gudem	Redlakunta	11KV	Huzurnagar	23.00	02.00	03.00	EL	Due to 11Kv jumper cutted	-
4		Kondamadugu	Kondamadugu	11KV	Bhongir	12.45	14.15	01.30	EL	11kv Line Snapped near Kondamadugu Mettu Villge	-
5		Addagudur	Ch.Ramaram	11KV	Bhongir	12.25	13.40	01.15	EL	11kv Line Snapped Near Addagudur Villge	-
6		Azeempet	Kanchanpally	11KV	Bhongir	13.15	17.50	03.35	EL	11kv Jumper Cut In Near Knchanpally Vllge	-
7		B.Vellemla	B.Vellemla	11KV	Nalgonda	09.00	14.30	05.30	EL	11KV Insulator failed	-
1	MDK	Bonthapally	Veerabadra	11KV	Gummadidala	09.35	10.40	01.05		B/D Due to Jumper Cut	-
1	RR E	Moula ali	Kailasagiri	11KV	Sainikpuri	19.52	20.42	00.50		11Kv Pin Insulator failed at Phase-II near Alluri Sitaramaraju (FOC Ganfadhar)	-
1	HYD S	Salarjung	Salarjung Museum	11KV	III	04.05	05.25	01.20	All Indication	7No Jumpers cut, 9No HG fuses B/o at Salarjung Museum & 2No. O/G Jumpers cut at SS	-
1	HYD C	Bathkamma Kunta	Saibaba Temple	11KV	II	13.02	14.18	01.16	EL	Kite Sticks fallen on lines at Saibaba Temple	-