

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No. of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		1		1		1			
7	RR(E)	168	403		2		2		2			
8	Hyd	194	1044									
	Total	606	3055	0	3	0	3	0	3	0	0	

Rural

S.No	Circle	No. of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849									
2	NLG	144	988	1	4	1	4	1	4			
3	MDK	107	933									
4	SDPT				2		2		2			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	1	6	1	6	1	6	0	0	
	Grand Total	1082	6468	1	9	1	9	1	9	0	0	

TSSPDCL - LMRC / Corporate office

Date: 18.01.2019

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	NLG	Dirincherla	Palakeedu	33KV	Huzurnagar	06.15	11.45	04.00	EL/OL	33Kv Bus Jumper Cut		-

TSSPDCL - LMRC / Corporate office

Date: 18.01.2019

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Chandupatla	Kunoor	11KV	Bhongir	07.00	09.15	02.15	E/L	11Kv Jumper Cut In near Kesaram (V)	-
2		Puligilla	Kerchpally	11KV	Choutuppal	11.05	12.50	01.45	E/L	Bird Fallen at Line near Puligilla (V)	-
3		G T Giri	G T Giri	11KV	Suryapet	08.05	09.30	01.25	E/L	11Kv Jumper cut	-
4		Raghunadapalem	Nakkagudem	11KV	Huzurnagar	08.00	11.00	03.00	E/L	11Kv JUMPER CUT	-
1	SDPT	Bekkal	Bairanpally	11KV	Siddipet	10.10	11.05	00.55		Rectified jumper cut	
2		Potharam	Potharam R	11KV	Siddipet	09.30	11.45	02.15		Rectified jumper cut	
1	RR N	GP Pally	Malla Reddy	11KV	Medchal	09.10	10.10	01.00	BD	11KV Pin Insulator failed at Brindavan Forest	-
1	RR E	Narapally	Prathap Singaram	11KV	Keesara	08.40	09.20	00.40		Tree fallen on 11kv line at Muktha Village	-
2		Singapur	RGK	11KV	Keesara	01.05	01.50	00.45		11KV Jumper cut at Modi Builder's	-