

TSSPDCL - LMRC / Corporate office

Date: 02.03.2019

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	RR N	132KV Medchal	33KV Nuthankal	33KV	Medchal	10.25	15.05	04.40	BD	33KV Line Phase to Phase & Rectified at Priyadarshini Hotel		-

TSSPDCL - LMRC / Corporate office

Date: 02.03.2019

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Tekumatla	Rainigudem	11KV	Suryapet	14.58	16.30	01.32	E/L	11Kv Insulator failed	-
2		Gondiryala	Chimiryala	11KV	Huzurnagar	06.30	09.00	02.30	E/L	11Kv Line Snapped	-
1	SDPT	Chityal	Thadoor	11KV	Husnabad	02.05	07.30	05.25		BD(11KV conductor snapped)	
2		Gandipally	Gandipally	11KV	Husnabad	00.00	07.20	07.20		BD(11KV/LT conductor snapped),1Ph ok	
1	RR S	Chandanagar	Madinaguda	11KV	GCB	04.55	06.10	01.15	BD	11KV AB Cable End Kit Failure at RTC Colony, Madinaguda.	-
1	RR E	Peerzatiguda	Shankar nagar	11KV	Keesara	16.02	16.32	00.30		Squarel fallen on T/F at Ram krishna nagar	-
2		CRPF	Chenapaur	11KV	Keesara	18.20	18.45	00.25		line petroling done no visiable falt founf & line Ab swicth open at Mallaguda	-
1	HYD C	Golconda	Darga Cable	11KV	Mehdipatanam	15.32	17.20	01.48	EL,OL-Rph	Conductor snapped at Karachi Bakrey & Twisted lines at D-Mart	-