

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No. of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550									
7	RR(E)	168	403									
8	Hyd	194	1044									
	Total	606	3055	0	0	0	0	0	0	0	0	

Rural

S.No	Circle	No. of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849									
2	NLG	144	988		6		6		6			
3	MDK	107	933	1	2	1	2	1	2			
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	1	8	1	8	1	8	0	0	
	Grand Total	1082	6468	1	8	1	8	1	8	0	0	

TSSPDCL - LMRC / Corporate office

Date: 05.03.2019

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MDK	Bollaram	Bollaram - IV	33KV	Patancheru	13.22	23.05	09.43		BD due to R&Y CTs Blasted at 132KV SS	Bollaram - IV	-

TSSPDCL - LMRC / Corporate office

Date: 05.03.2019

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Reddygudem	Gorantla	11KV	Suryapet	11.20	13.44	02.24		Insulator failure	-
2		Arlagadda	Tatikal	11KV	Nalgonda	12.20	15.00	02.40		11KV line disk failure	-
3		Palakeedu	Palakeedu	11KV	Huzurnagar	06.45	09.50	03.05		Jumper cut	-
4		Kandibanda	NB Gudem	11KV	Huzurnagar	09.30	12.15	02.45		Line snapped	-
5		Akupamula	Kodandampuram	11KV	Huzurnagar	10.40	14.00	03.20		Insulator failed	-
6		Buggavaigudem	Thimmareddygudem	11KV	Miryalaguda	15.45	17.00	01.15		Insulator failed	-
1	MDK	Kollur	Double Bedroom (Tellapur)	11KV	Sangareddy	13.35	18.00	04.25		BD due to Conductor snapped	-
2		Dundigal	Annaram	11KV	Patancheru	01.30	09.10	07.40		BD due to Bird fallen on line and Insulator failed	-