

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No. of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234		1		1		1			
6	RR(N)	54	550									
7	RR(E)	168	403									
8	Hyd	194	1044									
	Total	606	3055	0	1	0	1	0	1	0	0	

Rural

S.No	Circle	No. of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849									
2	NLG	144	988		2		2		2			
3	MDK	107	933									
4	SDPT			1	2	1	2	1	2			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	1	4	1	4	1	4	0	0	
	Grand Total	1082	6468	1	5	1	5	1	5	0	0	

TSSPDCL - LMRC / Corporate office

Date: 23.03.2019

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	SDPT	Husnabad	Katkur	33KV	Husnabad	00.00	16.55	16.55		BD,LA Failure at Meerjapur SS	Husnabad	No

TSSPDCL - LMRC / Corporate office

Date: 23.03.2019

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Palakaveedu	Bothalapalem	11KV	Huzurnagar	16.00	17.30	01.30	EL	Due to 11Kv line Snapped	-
2		Datharpally	Datharpally	11KV	Bhongir	06.00	06.45	00.45	OL	11 kv Jumper Cut Near Datharpally Village	-
1	SDPT	Rebarthy	Gagillapur Agl	11KV	Husnabad	16.30	19.00	02.30		BD,11KV CONDUCTOR SNAPPED	-
2		Katkur	Mallaram	11KV	Husnabad	11.20	12.30	01.10		BD,JUMPER CUT	-
1	RR S	IDPL	Moosapet	11KV	Kondapur	01.00	02.00	01.00		11KV Cable Failed at Moosapet (Back Feeding from Pownagar feeder)	-