

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT				4		4		4			
5	RR(S)	53	234									
6	RR(N)	54	550									
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044	2		2		2				
	Total	606	3055	2	5	2	5	2	5	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1		1		1				
2	NLG	144	988	1	13	1	13	1	13			
3	MDK	107	933									
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	2	13	2	13	2	13	0	0	
	Grand Total	1082	6468	4	18	4	18	4	18	0	0	

TSSPDCL - LMRC / Corporate office

Date: 06.05.19

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Nagarkurnool	Bijinapally	33KV	Nagarkurnool	06.25	07.25	01.00	E/L	Due to AB Switch Opened at 33KV Vatterm SS Supply Stood OK	Bijinapally	No
1	NLG	Shaligowraram	Nakrekal	33KV	Nalgonda	9:40	11:45	2:05	E/L	33KV Insulator failed and Jumper cut	Nakrekal	No
1	HYD N	132KV J' Hills	Madhapur (PTR-4)	33KV	Kalyan Ngr	04.40	05.40	01.00	OL-Rph	Tripped on OL-Rph	Madhapur (PTR-4)	Loads transferred onto 132KV Madhapur SS
2		132KV N.I.M.S	Muffakamja College	33KV	Kalyan Ngr	9:20	9:25	0:05	EL,OL	Lightening Arrester failed to 33KV Muffakamja College fdr at 132KV NIMS SS	Muffakamja College	Loads transferred onto 132KV Erragadda SS

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Mupparam	Yerrabelli	11KV	Miryalguda	17:00	17:48	0:48	E/L	11KV Jumper cut near village	No
2		Neelaigudem	Gantarao camp	11KV	Miryalguda	15.15	15.50	00.35	E/L	11KV Jumper cut near village	No
3		Tekumatla	Yandlapally	11KV	Suryapet	12.45	15.15	02.30	E/L	11KV Insulator failed	No
4		Dondapahad	Vajinepaly	11KV	Huzurnagar	11.50	14.20	02.30	E/L	11KV Line snapped	No
5		G.Malkapuram	Chinthalapalem	11KV	Huzurnagar	13.30	15.20	02.50	E/L	11KV Line snapped	No
6		Repala	V R Puram	11KV	Huzurnagar	13.30	15.30	02.00	E/L	11KV Jumper cut	No
7		Raigir	Raigir Agl	11KV	Bhongir	09.15	09.50	00.35	OL	11KV Jumper Snapped Near Raigir Village	No
8		Gurraladandi	Jampally	11KV	Bhongir	13.15	17.40	04.25	EL	11KV Jumper cut	No
9		Paladugu	Datthappagudem	11KV	Bhongir	16.00	17.00	01.00	OL	11KV Jumper Snapped Near Datthappagudem Village	No
10		Kapraipally	Rahimkhanpet	11KV	Bhongir	10.30	13.30	03.00	OL	HT/LT Near Rahimkhanpet Village	No
11		Mandollagudem	Peddakondur	11KV	Choutuppal	06.12	08.02	01.50	OL	11KV Line snapped at Poultry Farm Near Peddakondur Village	No
12		Jai kesaram	Jai kesaram	11KV	Choutuppal	09.00	13.24	04.24	EL	11KV Jumper cut	No
13		Jai kesaram	Assonigudem	11KV	Choutuppal	10:34	13:24	2:50	OL	Harvester Acccident Pole near Assonigudem Village.11 kv Pole Dammage. 3 DTR's OFF.	No
1	SDPT	Akunur	Dommta	11KV	Husnabad	14:20	16:45	2:25		Snake fallen on the line	No
2		Musthyal	Chunchanakota	11KV	Husnabad	10.20	16.15	05.55		Rectified 11KV line is intertwined	No
3		Marmoula	Dharmaram	11KV	Husnabad	13.00	14.00	01.00		Rectified 11KV line burnt	No
4		Marmoula	Dharmaram	11KV	Husnabad	15.00	16.40	01.40		Rectified 11KV line burnt	No
1	RR E	Saingapur	Singapur-2	11KV	Keesara	10:50	13:13	2:23		11KV End Kit Cable failed near SS Yard	No