

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No. of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		2		2		2			
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044		3		3		3			
	Total	606	3055	0	6	0	6	0	6	0	0	

Rural

S.No	Circle	No. of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	17		17		14		3		3 NO.s 33kv Still
2	NLG	144	988		7		7		7			
3	MDK	107	933		1		1		1			
4	SDPT				11		11		11			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	17	19	17	19	14	19	3	0	
	Grand Total	1082	6468	17	25	17	25	14	25	3	0	

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Mahabubnagar	Jadcherla	33KV	Mahabubnagar	18.30	21.50	03.20	E/L	Replacing of Disc Insulator at Sandarshini Hotel	Jadcherla	-
2		Mahabubnagar	Kodur(Machanpally)	33KV	Mahabubnagar	18.45	00.00	05.15	E/L	Not Rectified	Kodur(Machanpally)	
3		220KV SS Palkonda	Kodur	33KV	Mahabubnagar	18.10	21.03	02.53	E/L	Insulator Replaced at Eenadu Office	Kodur	
4		Kodangal	Kodangal	33KV	Vikarabad	19.50	23.30	03.40	E/L	4Nos Pin Insulator Replaced in Various Location	Kodangal	
5		Balanagar	Thommidirekula	33KV	Jadcherla	17.20	19.50	02.30	E/L&O/L	Tree Fallen on the Line	Thommidirekula	
6		Makthal	Jaklair	33KV	Narayanapet	17.45	23.25	05.40	E/L	Due to Heavy Gale & Wind Bijwar SS Was Dark	Jaklair	
7		Makthal	Paspula	33KV	Narayanapet	18.52	00.00	05.08	O/L	Not Rectified	Paspula	
8		Makthal	Krishna	33KV	Narayanapet	19.40	21.05	01.25	E/L	Due to Heavy Gale & Wind	Krishna	
9		Marikal	Kondapur	33KV	Narayanapet	07.35	07.50	00.15	E/L	Due to Heavy Gale & Wind	Kondapur	
10		Marikal	Koukuntla	33KV	Narayanapet	17.10	21.05	03.55	E/L	Due to Heavy Gale & Wind	Koukuntla	
11		Gadwal	Dharoor	33KV	Gadwal	16.40	23.15	06.35	E/L	Due to Heavy Gale & Wind	Dharoor	
12		Gadwal	Maldakal	33KV	Gadwal	16.24	00.00	08.36	E/L	Not Rectified	Maldakal	
13		220/33KV Singotam	Kollapur	33KV	Nagarkurnool	15.45	18.59	03.14	O/L	Insulator Failed at Yenmanbetla	Kollapur	
14		Shadnagar	Mamidipally	33KV	Shadnagar	16.45	19.10	02.25		R Phase Pin Binding Failed at 220KV SS	Mamidipally	-
15		Shadnagar	Rayalaseema	33KV	Shadnagar	16.40	20.10	03.30		Pole Damaged Near 220KV SS	Rayalaseema	-
16		Shadnagar	Glade Steel	33KV	Shadnagar	16.45	19.00	02.15		Conductor Snapped at Elikatta(V)	Glade Steel	-
17		Shadnagar	Salasar(Scan)	33KV	Shadnagar	16.45	19.00	02.15		Conductor Snapped at Elikatta(V)	Salasar(Scan)	-

TSSPDCL - LMRC / Corporate office

Date: 23.05.2019

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Urulugonda	Karkayalagudem	11kv	Huzurnagar	04.45	08.00	03.15	EL	Due to 11Kv Jumper cutted	-
2		Repala	Repala	11kv	Huzurnagar	04.00	06.25	02.25	EL	Due to 11Kv line snapped	-
3		Chanupally	Chanupally	11kv	Huzurnagar	14.30	17.10	02.40	EL	Due to 11Kv Jumper cutted	-
4		D Nagaram	W Kota	11kv	Suryapet	07.00	09.40	02.40	E/L	Insulator Failed	-
5		Gattuppal	Teratpally	11kv	Nalgonda	12.10	16.30	04.20	E/L	11KV Line Insulator Failur	-
6		Bondugula	Godumakunta	11kv	Bhongiri	10.50	11.30	00.40	EL	11kv Line snapped near Thimmaraj Gudem Village	-
7		Pamkunta	Singaram	11kv	Bhongiri	19.45	16.30	20.45	EL/OL	6no's 11kv pole Dammaged & 1no DTR 25KV Fallen at Singaram Village. Due to Heavy Gale & Wind	-
1	MDK	Gummadidala	Bell Remedies	11kv	Patancheru	07.40	09.05	01.25		BD due to Conductor snapped	
1	SDPT	Gouravelli	Gubbadi	11kv	Husnabad	08.50	11.00	02.10		11 KV line cut	-
2		Cherial	Sundaraya Nagar	11kv	Husnabad	06.10	00.00	17.50		Break down	-
3		Cherial	Rollabanda	11kv	Husnabad	08.55	14.25	05.30		Heavy gale and wind	
4		Komuravelli	Komuravelli 24 Hrs	11kv	Husnabad	01.45	02.10	00.25		Heavy gale and wind	
5		Komuravelli	Inapur AGL	11kv	Husnabad	07.00	10.00	03.00		Jumper cut	
6		Komuravelli	Komuravelli 7 hrs	11kv	Husnabad	08.25	10.00	01.35		Heavy gale and wind	
7		Komuravelli	Kadaverugu	11kv	Husnabad	08.25	10.00	01.35		11 KV line cut	
8		Chityala	Chityala	11kv	Husnabad	00.00	05.20	05.20		Pole Damaged	
9		Chityala	Dhommata	11kv	Husnabad	00.00	05.20	05.20		Heavy gale and wind	
10		Chityala	Thadoor	11kv	Husnabad	00.00	05.20	05.20		Heavy gale and wind	
11		Akunoor	Akunoor Agl	11kv	Husnabad	16.20	16.50	00.30		Heavy gale and wind	-
1	RR N	Medchal	IDA-I	11kv	Medchal	18.20	19.52	01.32	BD	11KV Line cut and replaced at Shamprey Company	-
2		GP Pally	Neighbourhood	11kv	Medchal	19.05	20.05	01.00	BD	11KV Line melted at Cheruvukatta	-
1	RR E	Moulali	Spectra	11kv	Sainikpuri	22.43	23.43	01.00		11kv Jumper Cut and touched to kasaram at BML Company IDA Moulali	-
1	HYD N	Jana Priya	I.O.L	11kv	IV	17.45	19.08	01.23	EL	UG Cable fault at IOL Road Crossing	-----
2	HYD C	Nampally	Red Hills	11kv	VII	12.28	15.34	03.06	EL	2No. Pin Insulators flash over at Himalaya Hotel	-----
3		Asif Nagar	N.S.F. Colony	11kv	VII	19.55	23.38	03.43	EL,OL-Rph	Pin Insulator flash over, Rph Jumper cut & Cable End Kit failed at Reddy Hotel	Arranged B/F on 11KV M.D.Lines fdr & 5No. DTR's added on 11KV Kakatiya Nagar fdr