

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	48	158									
2	NLG	18	406									
3	MDK	92	383									
4	RR(S)	40	201									
5	RR(N)	82	407		2		2		2			
6	RR(E)	38	360		5		5		5			
7	Hyd	186	1014		4		4		4			
	Total	504	2929	0	11	0	11	0	11	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	110	969									
2	NLG	150	948		4		4		4			
3	MDK	87	828	1		1		1				
4	RR(S)	31	338									
5	RR(N)	8	48									
6	RR(E)	18	89									
	Total	404	3220	1	4	1	4	1	4	0	0	
	Grand Total	908	6149	1	15	1	15	1	15	0	0	

TSSPDCL - LMRC / Corporate office

Date: 28.07.2017

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MDK	Medak	B.Bpur	33KV	Medak	19.45	22.20	02.35		B/D due to heavy rain & wind.	B.Bpur	-

TSSPDCL - LMRC / Corporate office

Date: 28.07.2017

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Marriguda	Kondur	11KV	Devarakonda	07.00	10.00	03.00	EL	Juper Cut	-
2		Mushampally	Mushampally Town	11KV	Nalgonda	08.30	10.30	02.00	EL	HT/LT Melting	-
3		S.V Collage	Layola Express	11KV	Suryapet	11.20	12.20	01.00	E/L	Bird fallen on the line	-
4		Mellacheruvu	V.R.Puram	11KV	Huzurnagar	04.00	07.00	03.00	OL	Due to 11Kv line Cutted near V.R.Puram village	-
1	RR N	Medchal	IDA-II	11KV	Medchal	12.48	14.00	01.12	BD	Incoming & Out going Jumper cut & replaced in SS	-
2		Subash Nagar	Bank Colony	11KV	Medchal	18.05	19.10	01.05	BD	11KVPin Insualtor failed at Raghavendra Colony	-
1	RR E	AUTO NAGAR	AUTO NAGAR	11KV	SAROOR NAGAR	07.05	08.05	01.00	EL	11KV PIN INSULATER BAINDING FAIL AT AUTO NAGAR	-
2		Moula-Ali	HMT	11KV	Sainikpuri	18.08	19.38	01.30		Tree branches fallen on 11Kv line at Evready Carbon Company (AE/Moula-Ali)	-
3		Moula-Ali	Jawahar Nagar	11KV	Sainikpuri	19.09	19.49	00.40		Lizard fallen on 11Kv line at RMP High School (Foc Naresh/Raju)	-
4		VP Nagar	VV Puram	11KV	Sainikpuri	18.30	19.00	00.30		11Kv Pin Insulator failed & rectified at Kakathiya Sai Padma Tower VV Puram (L.Insp Venkateshwarulu)	-
5		Kushaiguda	Saibaba Temple	11KV	Sainikpuri	19.00	19.40	00.40		11Kv Disk failed & Tree branches fallen & line snaped at Dhanpal Reddy Vencture (LM Srinu)	-
1	HYD N	Bowenpally	Plassy Lines	11KV	VI	17.22	19.00	01.38	No Indication	HT Jumper cut & Twisted lines at Plassy Lines	-----
2		I.I.C.T	Solex	11KV	V	18.10	19.30	01.20	EL,OL-Bph	Cable fault	Arranged B/F on 11KV St.Ann's fdr
1	HYD S	Miralam	Ranjan Colony	11KV	III	09.50	11.30	01.40	All Indication	3No. HT Jumper B/o & 2No. Disc Insulators flash over at Macca, Huda Colony & Sana Bakery	-
1	HYD C	Industrial Area	RTC X Road	11KV	II	02.15	03.25	01.10	EL,OL-Rph	Pin Insulator flash over & 11KV Jumper cut at 2nd Line AB Switch	-