

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	48	158									
2	NLG	18	406									
3	MDK	92	383									
4	RR(S)	40	201									
5	RR(N)	82	407									
6	RR(E)	38	360		2		2		2			
7	Hyd	186	1014									
	Total	504	2929	0	2	0	2	0	2	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	110	969									
2	NLG	150	948	1	6	1	6	1	6			
3	MDK	87	828		3		3		3			
4	RR(S)	31	338									
5	RR(N)	8	48									
6	RR(E)	18	89									
	Total	404	3220	1	9	1	9	1	9	0	0	
	Grand Total	908	6149	1	11	1	11	1	11	0	0	

TSSPDCL - LMRC / Corporate office

Date: 24.11.2017

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	NLG	Kolanupaka	Raghunathpur	33KV	Bhongir	07.55	15.15	07.20	EL	33KV Insulator failed & Jumper snapped 132KV SS	Kolanupaka	-

TSSPDCL - LMRC / Corporate office

Date: 24.11.2017

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Reddygudem	Reddygudem	11KV	Suryapet	05.00	08.30	03.30	E/L	Line cut	-
2		Dirincherla	Somaram	11KV	Huzurnagar	12.45	18.00	05.15	E/L	11 kv line snapped at Dirincherla village	-
3		Palakeedu	Bothalapalem	11KV	Huzurnagar	08.15	10.20	02.05	E/L	25 Kva Transformer failed at Bothalapalem village	-
4		Siripuram	Siripuram	11KV	Huzurnagar	09.40	10.50	01.10	E/L	11 kv line snapped at Siripuram village	-
5		Bethavolu	J P Gudem	11KV	Huzurnagar	15.00	19.00	04.00	E/L	11 KV Line snapped at JP GUDEM VILLAGE	-
6		Kistapuram	Tammaram	11KV	Huzurnagar	04.00	10.00	06.00	E/L	11 kv line snapped at Tammaram village	-
1	MDK	Lingaipally	Thanda	11KV	Medak	13.30	15.30	02.00		B/D due to Condtr Snapped	-
2		Shankarampet	Cheelapally	11KV	Medak	11.00	13.00	02.00		B/D due to Disc Failed	-
3		Kondapur	Terpole	11KV	Sangareddy	01.10	07.55	06.45		B/D due to Jumper cut	-
1	RR E	Poltechnic	Vishal	11KV	HABSIGUDA	02.20	04.05	01.45	E/L O/L	Cable fault at SS backside	-
2		Aushapur	Aushapur	11KV	Keesara	05.30	09.00	03.30		Pin insulator fail at aushapur village	-