

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	48	158									
2	NLG	18	406									
3	MDK	92	383									
4	RR(S)	40	201		1		1		1			
5	RR(N)	82	407		2		2		2			
6	RR(E)	38	360		2		2		2			
7	Hyd	186	1014		1		1		1			
	Total	504	2929	0	6	0	6	0	6	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	110	969	2	2	2	2	2	2			
2	NLG	150	948		2		2		2			
3	MDK	87	828									
4	RR(S)	31	338									
5	RR(N)	8	48									
6	RR(E)	18	89									
	Total	404	3220	2	4	2	4	2	4	0	0	
	Grand Total	908	6149	2	10	2	10	2	10	0	0	

TSSPDCL - LMRC / Corporate office

Date: 29.10.2017

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Narayanpet	Narayanpet Rural	11kv	Mahabubnagar	14.20	16.00	01.40		11KV Conductor cut Near Singaram (Vi)	-
2		Narayanpet	Jalalpur	11kv	Wanaparthy	15.00	19.30	04.30		11KV Insulator Damage at Jalalpur Gate (Vi)	-
1	NLG	Narkatpally	Mandra	11kv	Nalgonda	07.30	09.30	02.00	EL	11KV jumper cut	-
2		Koppel (K)	Koppel (K)	11kv	Nalgonda	11.30	13.00	01.30	EL	11Kv Insulator Fail	-
1	RR S	CBIT	CBIT	11kv	RJNR	22.45	23.43	00.58		11kv Line cut at Gandipet katta	-
1	RR N	J D M SS-I	JE T E L	11kv	Jeedimetla	02.05	04.20	02.15	BD	11kv AB Cable Failure At S L N Kanta Phase-I	-
2		J D M SS-II	Aparupa colony	11kv	Jeedimetla	18.20	18.55	00.35	BD	11kv Pin Insultor Failed At Jana Priya Ablock S R C naik nagar	-
1	RR E	MARUTHI NAGAR	YADAV NAGAR	11kv	SAROORNAGAR	08.35	10.09	01.34		11KV YADAV NAGAR LOAD BACK FEEDING TO HARIPURI & 11KV YADAV NAGAR FEEDER CUBULU FAIL	-
2		Keesara	Keesara town	11kv	Habsiguda	10.45	12.05	01.20		line pertoling done no visiable falt found	-
1	HYD S	Chanchalguda	Arya Samaj	11kv	Asmangadh	07.05	08.50	01.45	EL,OL	Snapped HT Line fallen on LT Lines at Akber X-Road	

TSSPDCL - LMRC / Corporate office

Date: 29.10.2017

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Kodangal	Peddanandigama	33kv	Mahabubnagar	07.05	09.30	02.25	E/L	Pin insulator replaced near ChinnaNandigama gate, Pylamadi gate	Peddanandigama	for Alternate Supply Arranged from 33KV Doulothad feeder at 9:30Hrs
2		Gadwal	Alwalpad	33kv	Gadwal	15.05	16.35	01.30	E/L	for Tree Branches Removing at Gonpad(V)	Alwalpad	-