

**Status Report on Breakdowns (Urban / Rural)****Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	48	158									
2	NLG	18	406									
3	MDK	92	383									
4	RR(S)	40	201		1		1		1			
5	RR(N)	82	407	1	7	1	7	1	7			
6	RR(E)	38	360									
7	Hyd	186	1014									
	<b>Total</b>	<b>504</b>	<b>2929</b>	<b>1</b>	<b>8</b>	<b>1</b>	<b>8</b>	<b>1</b>	<b>8</b>	<b>0</b>	<b>0</b>	

**Rural**

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	110	969	2	1	2	1	2	1			
2	NLG	150	948		6		6		6			
3	MDK	87	828	3	2	3	2	3	2			
4	RR(S)	31	338									
5	RR(N)	8	48									
6	RR(E)	18	89									
	<b>Total</b>	<b>404</b>	<b>3220</b>	<b>5</b>	<b>9</b>	<b>5</b>	<b>9</b>	<b>5</b>	<b>9</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>908</b>	<b>6149</b>	<b>6</b>	<b>17</b>	<b>6</b>	<b>17</b>	<b>6</b>	<b>17</b>	<b>0</b>	<b>0</b>	

TSSPDCL - LMRC / Corporate office

Date: 07.09.2017

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Makthal	Jaklaire	33KV	Mahabubnagar	12.35	15.25	02.50	E/L	Insulator Damaged and Conductor Cut near Lingampally Village		-
2		Marikal	Koukuntla	33KV	Mahabubnagar	20.50	21.35	00.45	E/L	Alternate Supply Arranged 33KV Devarkadra SS		-
1	MDK	Manoharabad	Kallakal	33KV	Toopran	17.25	18.15	00.50		B/D due to Disk Failure.		-
2		Gummadidala	AFA	33KV	Sangareddy	18.00	20.05	02.05		B/d due to Jumper cut		-
3		Pashamailaram	Nandigama	33KV	Sangareddy	18.45	22.10	03.25		B/d Due to insulator failure		-
1	RR N	132KV LGM Pet	33KV BE Vaccine	33KV	Medchal	16.45	19.02	02.17		BD Declared 33KV Pin Insulator Failed at Nekthar Company Opp		-

TSSPDCL - LMRC / Corporate office

Date: 07.09.2017

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Edira	Divitipally	11KV	Mahabubnagar	14.45	17.00	02.15		11KV Insulator Damage near Divitipally forest (V)	-
1	NLG	Dirsenapally	Miryala	11KV	Suryapet	07.00	09.30	02.30	E/L	11Kv Insulator failed	-
2		Pamanagundla	Pittampally	11KV	Nalgonda	03.00	07.30	04.30	E/L	11 KV Jumper Cut at SS-4	-
3		Urumadla	Yelikatte	11KV	Nalgonda	08.45	11.30	02.45	E/L	11 KV Line Insulator Fialure SS-21	-
4		Mushampally	Mushampally	11KV	Nalgonda	07.10	11.30	04.20	E/L	11 KV Line Insulator Fialure SS-36	-
5		Dondapadu	Kakatiya	11KV	Huzurnagar	08.40	11.20	02.40	EL	Due to Insulator failure near Kakatiya village	-
6		Munagala	Turkagudem	11KV	Huzurnagar	06.30	09.10	02.40	EL	Due to Bird fall on 11kv line near Turkagudem village	-
1	MDK	Narayanaraopet	Kondamrajpally	11KV	SIDDIPET	15.00	16.00	01.00		B/d due to Jumper cut	-
2		Narayanaraopet	Ghanpur	11KV	SIDDIPET	13.00	16.00	03.00		B/d due to Jumper cut	-
1	RR S	Kokapet	Babukhan	11KV	RJNR	04.19	06.55	02.36	B/D	11KV line snapped at Outer ring road	-
1	RR N	ICICI	Uniq-I	11KV	Medchal	16.21	18.01	01.40	BD	11KV Pin Insulator Failed at EPR Pharma	-
2		Kistapur	IDA Hanuman	11KV	Medchal	17.00	18.00	01.00	BD	Tree Branch fallen on the 11KV Line at Etukala company,Kistapur	-
3		Athiwelly	SPIC	11KV	Medchal	18.00	19.55	01.55	BD	11KV Pin Insulator Failed at Jayadharshini Road,Ravalkole Thanda	-
4		Ravalkole	Ravalkole	11KV	Medchal	16.31	17.50	01.19	BD	11KV Pin Insulator Failed at Cheruvukatta,Ravalkole	-
5		Mayurinagar	Ramnareshnagar	11KV	Kuktpally	10.50	12.25	01.35	BD	11kv Insulator Failed at Mayuri Nagar Ladies Hostel	-
6		Nizampet	Srinivasa Colony	11KV	Kuktpally	11.30	13.50	02.20	BD	11kv AB Cable Replaced at Chaitanya College	-
7		Suraram	Rajev Gandhinagar	11KV	Jeedimetla	13.10	14.04	00.54	BD	11kv line Snaped at Rajiv Gandhinagar	-