

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No. of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550									
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044		1		1		1			
	Total	606	3055	0	2	0	2	0	2	0	0	

Rural

S.No	Circle	No. of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849									
2	NLG	144	988		8		8		8			
3	MDK	107	933		1		1		1			
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	0	9	0	9	0	9	0	0	
	Grand Total	1082	6468	0	11	0	11	0	11	0	0	

TSSPDCL - LMRC / Corporate office

Date: 30.12.2018

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Phanigiri	Etooru	11KV	Suryapet	07.30	09.10	01.40	E/L	Disc flashover	-
2		N.B.Gudem	Redlakunta	11KV	Huzurnagar	05.15	08.20	03.05	EL	Due to 11Kv jumper cutted	-
3		Ananthagiri	Ameenabad	11KV	Huzurnagar	18.00	19.05	01.05	EL	Due to 11Kv disk failure	-
4		Ravipahad	Burkacherla	11KV	Huzurnagar	13.45	16.30	02.45	EI	Due to 11Kv jumper cutted	-
5		Nandanam	Nagireddypally	11KV	Bhongir	08.30	10.30	02.00	EL	Laiting Arester Fail Near Pallempu Villge	-
6		Nemaragomilla	Jiyapally	11KV	Bhongir	15.52	17.20	01.28	EL	Tree Branches Fallen at Line near Jiyapally Villge	-
7		Alair	Chinna Kandukur	11KV	Bhongir	08.45	15.50	07.05	EL	11kv Line Snapped at Ramasamudram Villge	-
8		Pamkunta	Singaram	11KV	Bhongir	15.50	17.20	01.30	EL	Stay Wire Sanpped & Fallen To 11kv Line near Singaram Villge	-
1	MDK	Bollaram - II	Rupa	11KV	Sangareddy	15.55	20.15	04.20		BD Due to conductor snapped near Ptancheruvu	-
1	RR E	VP Nagar	RK Puram	11KV	Sainikpuri	16.35	17.15	00.40		Kite stick fallen on 11Kv line at Sree colony near Bhumika Residency (L.Insp Koteswar Rao)	-
1	HYD S	Petlaburz	Shah Gunj	11KV	III	16.40	17.50	01.10	OL-Rph	HT Line snapped at Naaz Hotel	-