

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	RR(S)	53	234									
5	RR(N)	54	550									
6	RR(E)	168	403		1		1		1			
7	Hyd	194	1044									
	Total	606	3055	0	1	0	1	0	1	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849		1		1		1			
2	NLG	144	988	1	2	1	2	1	2			
3	MDK	107	933	1		1		1				
4	RR(S)	58	396									
5	RR(N)	38	114									
6	RR(E)	22	133									
	Total	476	3413	2	3	2	3	2	3	0	0	
	Grand Total	1082	6468	2	4	2	4	2	4	0	0	

TSSPDCL - LMRC / Corporate office

Date: 23.03.18

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Janampet	Water works	11KV	Jadcherla	13.25	13.55	00.30		11KV Wire cut near Vemula road	No
1	NLG	Ponugodu	Ponugodu	11KV	Huzurnagar	14:50	17:50	3:00	EL	11 KV Insulator failed at Ponugodu village	No
2		Chilukur	Kondapuram	11KV	Huzurnagar	10.10	12.20	02.10	EL	11 KV Jumper cut at RC Nagar village	No
1	RR E	Aushapur	Edulabad AGL	11KV	Keesara	4:10	6:20	2:10		No visible fault	No

TSSPDCL - LMRC / Corporate office

Date: 23.03.18

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	NLG	Aitipamula	Kethepally	33KV	Nalgonda	7:00	8:29	1:29		33 KV line Insulator failed	Kethepally	No
1	MDK	Bollaram	Coca Cola	33KV	Sangareddy	20:20	16:35	20:15		Cable kit failed and tree branch fallen at Bollaram	Coca Cola	No