

**Status Report on Breakdowns (Urban / Rural)****Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	48	158									
2	NLG	18	406									
3	MDK	92	383									
4	RR(S)	40	201									
5	RR(N)	82	407		5		5		5			
6	RR(E)	38	360		1		1		1			
7	Hyd	186	1014		1		1		1			
	<b>Total</b>	<b>504</b>	<b>2929</b>	<b>0</b>	<b>7</b>	<b>0</b>	<b>7</b>	<b>0</b>	<b>7</b>	<b>0</b>	<b>0</b>	

**Rural**

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	110	969		1		1		1			
2	NLG	150	948		4		4		4			
3	MDK	87	828									
4	RR(S)	31	338									
5	RR(N)	8	48									
6	RR(E)	18	89									
	<b>Total</b>	<b>404</b>	<b>3220</b>	<b>0</b>	<b>5</b>	<b>0</b>	<b>5</b>	<b>0</b>	<b>5</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>908</b>	<b>6149</b>	<b>0</b>	<b>12</b>	<b>0</b>	<b>12</b>	<b>0</b>	<b>12</b>	<b>0</b>	<b>0</b>	

TSSPDCL - LMRC / Corporate office

Date: 10.08.2017

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Rajapur	Salguti	11KV	Jadcherla	12.15	15.55	03.40		11Kv AB Switch Failure Near Salgutti Company	-
1	NLG	Ravulapally	Manapuram	11KV	Suryapet	07.45	10.25	02.40	E/L	11Kv Insulator faild	-
2		Addaguduru	Ch.Ramaram	11KV	Bhongir	00.00	05.30	05.30	E/L	11Kv Line snapped at Ramaram	-
3		Mattapally	Sulthanpuram	11KV	Huzurnagar	07.30	10.30	03.00	E/L	11kv jumper cut near Janakinagar thanda (v)	-
4		Repala	Narsimhalagudem	11KV	Huzurnagar	06.00	09.00	03.00	E/L	11kv Disk failure near Narsimhalagudem (v)	-
1	RR N	Mathrusrinagar	Mathrusrinagar	11KV	Gachibowli	15.30	17.45	02.15	BD	Due To Heavy Rain. 11KV Disk Failure near Plot no-718 at Mathrusrinagar.	-
2		Mathrusrinagar	Kalyan Garden	11KV	Gachibowli	17.05	19.45	02.40	BD	11KV Line Patrolling. 11KV LABS Opened.	-
3		Papireddy Colony	Dubey Colony	11KV	Gachibowli	16.50	19.00	02.10	BD	Post Off Insulator Failure at Dubey Colony.	-
4		Yellampet	IDA	11KV	Medchal	07.30	08.30	01.00	BD	11KV Pin Insulator touched to cross arm at Sangam Company	-
5		Gowdavelly	Ayodhya	11KV	Medchal	19.20	21.20	02.00	BD	11KV Disc failed & Replacement at Ayodhya X road	-
1	RR E	PEDDA AMBERPET	KUNTLOOR	11KV	SAROOR NAGAR	05.30	07.30	02.00	EL	TREE BRACHANS FALL ON 11KV LINE AT KUNTLOOR	-
1	HYD N	E.N.T	Rang Mahal	11KV	IX	18.55	20.40	01.45	EL,OL-R&Bph	RMU Point UG Cable burntout at S.B.I	-