

TSSPDCL - LMRC / Corporate office

Date: 29.08.17

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MDK	Manoharabad	Masaipet	33KV	Toopran	17:40	19:35	1:55		Tree branches fallen on the line at Bharath Check post	Masaipet	No

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Dudyal	Alaid	11KV	Mahabubnagar	02.50	07.30	04.40		11KV Disc failure at Allikhanpally (V)	No
2		Kosgi	Nacharam	11KV	Mahabubnagar	05.20	11.40	06.20		11KV Insulator Damage at Chandravancha (V)	No
3		Kosgi	Bogaram	11KV	Mahabubnagar	08.10	11.20	03.10		11KV Conductor cut at Bhakthimalla (V)	No
4		Pasupula	Satyaram	11KV	Mahabubnagar	06.30	13.50	07.20		11KV Conductor cut at Goplapur (V)	No
5		Kotakonda	Bommanpad	11KV	Mahabubnagar	10.10	12.30	02.20		11KV Conductor cut at Kamsanpally (V)	No
6		Kotakonda	Bandagonda	11KV	Mahabubnagar	10.30	12.20	01.50		11KV Insulator Failure at Ganimonithanda (V)	No
7		Parpally	Achrayapur	11KV	Mahabubnagar	03.00	08.20	05.20		11KV Tree fallen on conductor at Jamulapur (v)	No
8		Hanwada	Madaram	11KV	Mahabubnagar	02.45	09.10	06.25		11KV Insulator Failure at Madaram (V)	No
1	NLG	Thungathurthy	Vempaty	11KV	Suryapet	10.35	13.30	02.55	E/L	Insulator failed	No
2		Sirikonda	Lalthanda	11KV	Huzurnagar	15.00	19.00	04.00	E/L	11KV Insulator failed at Lalthanda village	No
3		Janpahad	Shunyapahad	11KV	Huzurnagar	16.00	19.00	03.00	E/L	11KV Line snapped at Shunyapahad village	No
4		M.R Gudem	Baswapur	11KV	Bhongir	00.00	04.30	04.30	E/L	HT/LT	No
5		B.p.pally	revanpally	11KV	Bhongir	07.30	10.30	03.00	E/L	11KV Line snapped Bhongir	No
6		Chamapur	singaram	11KV	Bhongir	06.00	10.00	04.00	E/L	Tree Branches fallen on the line	No
1	MDK	B.B.Pur	B.B.Pur	11KV	Medak	12.45	16.05	03.20		11KV Line cut at Shalipet	No
2		Rajpally	Khajipally	11KV	Medak	18.00	19.30	01.30		Tree Branches fallen on the line	No
3		M. Bhupathipur	Guttakindipally	11KV	Medak	10.50	14.20	03.30		Tree Branches fallen on the line	No
4		Reddy pally	Reddy pally	11KV	Medak	17.30	19.00	01.30		11KV Disc failed	No
5		Venkatrapet	Venkatrapet	11KV	Medak	07.20	12.10	04.50		Due to LT line Cut	No
6		Narsingi	Narsingi	11KV	Medak	13.00	15.00	02.00		Due 11KV Line cut	No
7		Narsingi	Papannapet Agl	11KV	Medak	14.00	18.00	04.00		Due 11KV Line cut	No
8		Nangunoor	Nangunoor Town	11KV	Siddipet	10.00	12.00	02.00		Due Disc failed	No
9		Nangunoor	Nagarajupally	11KV	Siddipet	12.05	14.30	02.25		Due Insulator failed	No
10		Gonepally	Mandapally	11KV	Siddipet	11.22	12.20	00.58		Due Insulator failed	No
1	RR S	MD Pally	Laxmiguda	11KV	Rajendranagar	00.35	01.50	01.15		HT Service CTPT failed at Mahaveer college	No
2		Kismathpur	LV prasad	11KV	Rajendranagar	17.50	18.55	01.05		11KV Insulator failed at LV prasad Eye institute	No
3		Rajendranagar	Rajendranagar	11KV	Rajendranagar	00.40	01.45	01.05		CTPT Failed at fish building at SS	No
4		Ibrahimbagh	Military-I	11KV	Rajendranagar	17.30	18.20	00.50		11KV Insulator Failed at neknapur	No
5		Manikonda	Friends Colony	11KV	Rajendranagar	17.41	19.20	01.39		11KV Insulator Failed at meerabai apartment	No
6		Chowdapur	mandipal	11KV	Vikarabad	02.00	04.10	02.10		11KV Insulator failed	No
7		Madanpally	Madanpally	11KV	Vikarabad	09.30	11.30	02.00		11KV Insulator failed	No

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	RR N	Balajinagar	Kukatpally	11KV	Kukatpally	00.11	01.05	00.54		11kv Srinivasa feedar AB Switch opened at Shivanand Hospital , Kukatpally	No
2		Mayurinagar	Prashanth Nagar	11KV	Kukatpally	15.00	15.45	00.45		11kv line AB Cable failed at phase-II & R L City line AB Opend	No
3		Guntur Vikas	Aparna	11KV	Kukatpally	14.40	15.30	00.50		No visible fault	No
4		Guntur Vikas	Co-Ca-Cola	11KV	Kukatpally	14.50	15.32	00.42		No visible fault	No
5		Guntur Vikas	Co-Ca-Cola	11KV	Kukatpally	15.40	16.15	00.35		11kv line Jumper cut at NS Engineer Company	No
6		Guntur Vikas	Aparna	11KV	Kukatpally	17.20	18.36	01.16		11kv line Pin Insulator failed at Beside Aparna Company	No
7		Nizampet	Nizampet	11KV	Kukatpally	14.50	17.10	02.20		11kv line Disc insulator failed at Kousik Apt Nizmpet	No
8		Bachupally	SMS	11KV	Kukatpally	18.15	19.30	01.15		11kv line Endkit failed at Bollaram X Road	No
9		Aleap	Doctors Colony	11KV	Jeedimetla	17.20	17.45	00.25		Tree branches fallen the AB Switch near Ravi Apt at SS Back side	No
10		Bandamadaram	Rock Sand	11KV	Medchal	13.10	14.25	01.15		11KV Pin Insulator failed at Mallanna Temple, Girmapur	No
11		GP Pally	Maisammaguda	11KV	Medchal	17.50	19.20	01.30		11KV Disc failed at DRS School opp,Maisammaguda	No
1	RR E	Mallapur	Noma	11KV	Habsiguda	14.45	15.30	00.45	EL/OL	No visible fault	No
2		Mallapur	IDA	11KV	Habsiguda	17.55	18.55	01.00	EL/OL	No visible fault	No
3		Mallapur-2	Laxmi Narsimha	11KV	Habsiguda	00.17	01.17	01.00		11KV Cable failed	No
4		Mallapur-2	Laxmi Narsimha	11KV	Habsiguda	14.28	15.08	00.40		11KV Jumper cut	No
5		Ramanthapur	Dooradarshan	11KV	Habsiguda	14.16	15.40	01.24		Tree branches fallen on 11KV Line	No
6		Chengicherla	Chengicherla	11KV	Keesara	09.25	10.10	00.45		Tree fallen on 11KV Line at Venkata Sai Nagar	No
7		Aushapur	Sandupatlaguda	11KV	Keesara	01.00	04.00	03.00		11KV 3Nos Pin insulator failed at Eduabad & Sandupatlaguda	No
1	HYD N	Gymkhana	Pared Ground	11KV	Sec'bad	17.35	18.47	01.12	EL	Tree branches fallen on lines at Pared Ground	No
1	HYD S	Gosha Mahal	Gosha Mahal Road	11KV	Begumbazar	04.54	06.35	01.41	EL,OL-R&Yph	Pin Insulator flash over at Ravi Petrol Pump	No
1	HYD C	Nampally	Amba Hospital	11KV	Mehdipatnam	00.07	01.24	01.17	EL	Stick fallen on Lines at Bazarghat	No
2		Nampally	V.N.Colony	11KV	Mehdipatnam	05.09	07.24	02.15	EL	Cable fault	Arranged B/F on 11KV Zaheera Masjid & 11KV P.S.Nagar fdrs
3		Golconda	Aditya Nagar OH	11KV	Mehdipatnam	17.15	19.35	02.20	EL	Tree branches fallen on lines at Sana Hotel	No
4		Golconda	Darga Cable	11KV	Mehdipatnam	17.17	19.17	02.00	EL	Tree branches fallen on lines at Grave Yard	Arranged partial loads B/F on 11KV Narayanamma Engi.College fdr

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	48	158									
2	NLG	18	406									
3	MDK	92	383									
4	RR(S)	40	201		7		7		7			
5	RR(N)	82	407		11		11		11			
6	RR(E)	38	360		7		7		7			
7	Hyd	186	1014		6		6		6			
	Total	504	2929	0	31	0	31	0	31	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	110	969		8		8		8			
2	NLG	150	948		6		6		6			
3	MDK	87	828	1	10	1	10	1	10			
4	RR(S)	31	338									
5	RR(N)	8	48									
6	RR(E)	18	89									
	Total	404	3220	1	24	1	24	1	24	0	0	
	Grand Total	908	6149	1	55	1	55	1	55	0	0	